1
Message us

Digitally signed by Neruşceac Irina
Date: 2024.10.06 17:55:08 EEST
Reason: MoldSign Signature
Location: Moldova

USD $ | Moldova

1


1 Second Measure Temperature
Avoid cross infection and instant readings
3-5 cm

HOOSING THE TEMPERATURE UNIT
1.In the switch on state, Press "MODE" button for 2 seconds,
The screen will display "F1".
2. Press "MODE" button to transfer between degree Celsius and Fahrenheit.
3. Comfirm by pressing "MEM" button.
91.7
37.1

1