

Mounting diagram for VARISIL type HE option S3D2 surge arresters

Parts supplied

- ① Surge arrester element (x1)
- ② Insulating bracket with built-in disconnecter (x1)
- ③ HM12-35 screw (x1)
- ④ WZ12 spring washer (x1)
- ⑤ Terminal clamp (x2)
- ⑥ Hm12 nut (x2)
- ⑦ L12 flat washer (x1)
- ⑧ D12 rubber washer (x1)

