

Cessna 172S

SUPPLEMENT No.

Vaccine Scattering

Registration No.	OK - VUT
Serial No.	172S10207

This supplement supplies the information necessary for the efficient operation of the airplane when the Vaccine Scattering is installed. The information contained within this supplement is to be used in conjunction with the complete AFM.

This supplement is a permanent part of this AFM and must remain in this AFM at all times when the Vaccine Scattering is installed.

This Flight Manual supplement is EASA approved under Approval No.: 10035523

Date : 28. 6. 2011

CONFORM CU ORIGINALUL

ELMONTA a. s.
Vratimovská 69/335
718 00 Ostrava - Kramčický
DIČ: CZ47155086

Vaccine Scattering

Rev. No.	Revised Pages	Description of Revision	CAA Approved	Date

September 03/13

ELMONTEX a.s.
Vratimovská 69/335
718 00 Ostrava - Kunčičky
DIČ: CZ47155086

CESSNA
MODEL 172S

SECTION 9
SUPPLEMENTS


LOG OF APPROVED SUPPLEMENTS

SUPP. NO.	SUPPLEMENT NAME	REVISION LEVEL	EQUIPMENT INSTALLED
--------------	-----------------	-------------------	------------------------

	Vaccine Scattering	<u>1/4</u>	
--	--------------------	------------	--

This Flight Manual supplement is EASA approved under Approval
No.: 10035523

Date : 28. 6. 2011



September 03/13

NZ AE/128-DLP1

1/2

CONFORM CU ORIGINALUL

ELMONTA a.
Vratimovská 69/335
718 00 Ostrava - Kunčický
DIČ: CZ47155086
-9-

SECTION 1
GENERAL - Not Affected

SECTION 2
LIMITATIONS

If the the dropping equipment is installed, the aeroplane must be operated in the NORMAL CATEGORY only.
The speed is to be kept between 80 -105 KIAS during the vaccine application process.
It is required that except for the pilot the dropping equipment operator is on board of the plane as well.

SECTION 3
EMERGENCY PROCEDURES - Not Affected

SECTION 4
NORMAL PROCEDURES - Not Affected

SECTION 5
PERFORMANCE - Not Affected

SECTION 6
WEIGHT & BALANCE/EQUIPMENT LIST - Not Affected

SECTION 7
AIRPLANE & SYSTEMS DESCRIPTIONS

The dropping equipment for rabies vaccine scattering is installed. The dropping equipment operator sits on the right seat rotated backwards during takeoff and landing. The operator's seat belts shall be fastened.

September 03/13

NZ AE/128-DLP1

3/4

CONFORM CU ORIGINALUL

ELMONTEX s.r.o.
Vratimovská 69/335
718 00 Ostrava - Kunčický
DIČ: CZ47155086

PILOT'S OPERATING HANDBOOK
SUPPLEMENT

Vaccine Scattering

The engine power setting – as required to keep the horizontal flight.
The dropping equipment operator does not have to be fastened by
seat belts during the dropping equipment operation.

SECTION 8
AIRPLANE HANDLING, SERVICE & MAINTENANCE
- Not Affected

SECTION 9
SUPPLEMENTS

Issued Vaccine Scattering supplement.

CONFORM CU ORIGINALUL

ONTEX a. s.
Vojnovská 69/335
215 01 Bystřava - Kuncický
47155086