


Clearing a function

Select the location to clear and then select [Delete].

(3) Assigning to custom switches




Procedure

1. Select [Custom SW] from the Input Device list.
2. Select the switch to assign.
3. From the Mode column, select the desired mode.
4. From the Item column, select the functions to assign.

Clearing a function

Select the switch to clear and then select [Delete].

(4) Assigning to custom foot switches



Procedure

1. Select [Custom-Foot SW] from the Input Device list.