


**PARAMETRII FIZICO-MECANICI
PENTRU CARTON ONDULAT**

| SF intreprindere | | | GOST - 9142 | | |
|------------------|------------------------------|----------------------------------|-------------|------------------------------|---------------------------------|
| Marca | Rezistenta la plesnire (kPa) | Rezistenta la compresiune (kN/m) | Marca | Rezistenta la plesnire (kPa) | Rezistenta la compresiune(kN/m) |
| | МИНИМУМ | | | | |
| K 3-18 | 3,00 | 1,40 | | | |
| K 3-18+ | 3,50 | 1,60 | | | |
| K 3-19 | 4,00 | 1,80 | | | |
| K 3-19+ | 4,50 | 2,00 | | | |
| K 3-20 | 5,00 | 2,20 | T21 | 7,00 | 2,20 |
| K 3-20+ | 5,50 | 2,40 | | | |
| K 3-21 | 6,00 | 2,70 | | | |
| K 3-21+ | 7,00 | 3,00 | T22 | 9,00 | 3,00 |
| K 3-22 | 8,00 | 3,30 | | | |
| K 3-22+ | 9,00 | 3,60 | | | |
| K 3-23 | 10,00 | 3,90 | T23 | 11,00 | 3,80 |
| K 3-23+ | 11,00 | 4,20 | | | |
| K 3-24 | 11,50 | 4,60 | T24 | 12,00 | 4,60 |
| K 3-24+ | 12,00 | 5,00 | | | |
| K 3-25 | 12,50 | 5,40 | T25 | 13,00 | 5,40 |
| K 3-25+ | 13,00 | 5,80 | | | |
| K 3-26 | 14,00 | 6,20 | T26 | 15,00 | 6,20 |
| K 3-26+ | 15,00 | 6,60 | | | |
| K 3-27 | 16,00 | 7,00 | T27 | 17,00 | 7,00 |
| K 3-27+ | 17,00 | 7,40 | | | |
| K 3-28 | 18,00 | 7,80 | | | |
| K 5-29 | 8,00 | 3,50 | | | |
| K 5-29+ | 9,00 | 4,00 | | | |
| K 5-30 | 10,00 | 4,50 | | | |
| K 5-30+ | 11,00 | 5,00 | П31 | 11,00 | 5,00 |
| K 5-31 | 12,00 | 5,50 | | | |
| K 5-31+ | 13,00 | 6,00 | | | |
| K 5-32 | 14,00 | 6,50 | П32 | 14,00 | 6,00 |
| K 5-32+ | 15,00 | 7,00 | | | |
| K 5-33 | 16,00 | 7,50 | | | |
| K 5-33+ | 17,00 | 8,00 | П33 | 17,00 | 8,00 |
| K 5-34 | 18,00 | 8,50 | | | |
| K 5-34+ | 19,00 | 9,00 | | | |
| K 5-35 | 20,00 | 9,50 | П34 | 20,00 | 10,00 |
| K 5-35+ | 21,00 | 10,00 | | | |
| K 5-36 | 22,00 | 10,50 | | | |
| K 5-36+ | 23,00 | 11,00 | П35 | 23,00 | 12,00 |
| K 5-37 | 24,00 | 12,00 | | | |
| K 5-37+ | 25,00 | 13,00 | | | |
| K 5-38 | 26,00 | 14,00 | П36 | 25,00 | 15,00 |

ПРОДАВЛИВАНИЕ



РЕЗИСТЕНТА LA PLESNIRE
РАЗРЫВ НА СТИБАХ



ТОРЦЕВОЕ СЖАТИЕ

