

CESSNA
MODEL 172S

SECTION 9
SUPPLEMENTS

PILOT'S OPERATING HANDBOOK
SUPPLEMENT

Vaccine Scattering

Cessna 172S

SUPPLEMENT No.

LOG OF APPROVED SUPPLEMENTS

SUPP. NO. SUPPLEMENT NAME REVISION LEVEL EQUIPMENT INSTALLED


Vaccine Scattering 9

Registration No.	OK - ELR
Serial No.	172S10151

Vaccine Scattering

This Flight Manual supplement is EASA approved under Approval
No.: 10035523

Date : 28. 6. 2011



May 05/11

NZ AE/128-DLP1

1/2

This supplement supplies the information necessary for the efficient operation of the airplane when the Vaccine Scattering is installed. The information contained within this supplement is to be used in conjunction with the complete AFM.
This supplement is a permanent part of this AFM and must remain in this AFM at all times when the Vaccine Scattering is installed.

This Flight Manual supplement is EASA approved under
Approval No.: 10035523

Date : 28. 6. 2011

ELMONTEX a.s.
Vratimovská 69/335
718 00 Ostrava - Kunčický
DIČ: CZ47155086

May 05/11

NZ AE/128-DLP1

1/4

CONFORM CU ORIGINALUL

LOG OF REVISION

Rev. No.	Revised Pages	Description of Revision	CAA Approved	Date

Intentionally left blank

2/2

NZ AE/128-DLP1

May 05/11

2/4

NZ AE/128-DLP1

May 05/11

ELMONTEX a. s.

Vratimovská 69/335

718 00 Ostrava - Kunčičky

DIČ: CZ47155086

CONFORM CU ORIGINALUL

**PILOT'S OPERATING HANDBOOK
SUPPLEMENT**

Vaccine Scattering

**SECTION 1
GENERAL - Not Affected**

**SECTION 2
LIMITATIONS**

If the the dropping equipment is installed, the aeroplane must be operated in the NORMAL CATEGORY only.
The speed is to be kept between 80 -105 KIAS during the vaccine application process.
It is required that except for the pilot the dropping equipment operator is on board of the plane as well.

**SECTION 3
EMERGENCY PROCEDURES - Not Affected**

**SECTION 4
NORMAL PROCEDURES - Not Affected**

**SECTION 5
PERFORMANCE - Not Affected**

**SECTION 6
WEIGHT & BALANCE/EQUIPMENT LIST - Not Affected**

**SECTION 7
AIRPLANE & SYSTEMS DESCRIPTIONS**

The dropping equipment for rabies vaccine scattering is installed. The dropping equipment operator sits on the right seat rotated backwards during takeoff and landing. The operator's seat belts shall be fastened.

May 05/11

NZ AE/128-DLP1

3/4

CONFORM CU ORIGINALUL

ELMONTEX a. s.
Vratimovská 69/335
718 00 Ostrava - Kuntčický
DIČ: CZ47155086

Vaccine Scattering

PILOT'S OPERATING HANDBOOK
SUPPLEMENT

The engine power setting – as required to keep the horizontal flight.
The dropping equipment operator does not have to be fastened by
seat belts during the dropping equipment operation.

SECTION 8

AIRPLANE HANDLING, SERVICE & MAINTENANCE

- Not Affected

SECTION 9

SUPPLEMENTS

Issued Vaccine Scattering supplement.

4/4

NZ AE/128-DLP1

May 05/11

CONFORM CU ORIGINALUL

ELMONTEX a. s.
Vratimovská 69/335
718 00 Ostrava - Kunčičky
DIČ: CZ47155086

