


Necesitatea remedierii urmatoarelor defectiuni

Nr.	Locatia	Model generatorului	Defectiunea	Pretul fara TVA (lei)	Pretul cu TVA (lei)
1	SPF Criva	APD 20A 15kva	Panou de comanda	5 000.00	6 000.00
2	SPF Otaci	APD 33A 20kva	Panou de comanda	5 000.00	6 000.00
3	Tudora turn termo	GYW-8 T5 7.2 kva	ARR defectat	2 500.00	3 000.00
4	SPF Poganesti	APD 20A 15kva	Panou de comanda	5 000.00	6 000.00
5	SPF Leuseni-1	APD 20A 15kva	Panou de comanda	5 000.00	6 000.00
6	SPF Taxobeni	APD 33A 20kva	Panou de comanda	5 000.00	6 000.00
7	TP04 Horesti	APD 33A 20kva	Panou de comanda, SRR defectat	7 500.00	9 000.00
TOTAL:				35 000.00	42 000.00

Semnat:  Numele, Prenumele: Midoni Vasile În calitate de: Director general

Ofertantul: TeCaPro SRL Adresa: mun. Chisinau, str. Bucuresti 42/6A

