



注意事項 CAUTIONS

■本產品電池出廠時，不得直接進行放電。
首次使用務必：

- 1、將單體電池進行恆電流0.3CA-0.5CA充電至限制電壓3.8V後停止充電。
- 2、如電池組首次使用必須依據我司電池《使用說明書》標準充放電(表三)進行充滿電後方可使用放電。
- 3、電池串聯使用必須採用符合本產品充電設備及BMS結合才能使用。

■電池在運輸過程中，不得受劇烈機械衝撞、曝曬、雨淋。

■電池在裝卸過程中，應輕搬輕放，嚴禁摔擲、翻滾、重壓。

■不能重壓，不能重疊放置。

■產品貯存在溫度為 $25^{\circ}\text{C} \pm 5^{\circ}\text{C}$ 的乾燥、清潔、通風的倉庫內。

■不受陽光直射擊，遠離熱源不少於2米。

■嚴禁短路。

■When shipped from the factory, this cell CANNOT be discharged directly under any condition.

Before the first use :

1. The single cell must be charged at constant current of 0.3CA-0.5CA and the cell should not be charged till the charging voltage reaches 3.8V .

2. The battery pack must be fully charged under the instruction of Operator's Manual -- Battery Pack's Standard Charge and Discharge Current and Voltage (Chart 3) .

3. If the batteries are used in series, they must be adopted with the proper charging equipment and BMS accordingly.

■Avoid shock, sunshine and rainwater in the shipment

■Do not knock, welter or stress during loading and unloading

■Do not lap over.

■The battery should be stored in clean, dry and ventilated warehouse at temperature of $25^{\circ}\text{C} \pm 5^{\circ}\text{C}$

■Be away from direct sunlight and away from heat no less than 2 meters.

■Short circuit is not allowed.

国际销售
International Sales

雷天温斯顿电池有限公司
THUNDER SKY WINSTON BATTERY LIMITED

中国生产基地
Production Base in China

东方醒狮储能电池有限公司
ORIENTAL SMART LION ENERGY STORAGE BATTERY LIMITED

TEL: 86-0596-818 6789
Fax: 86-0596-818 6678

<http://www.thundersky-winston.com>
E-mail: winston@thundersky-winston.com

中国福建省漳州市长泰经济开发区
CHANGTAI INDUSTRIAL ZONE, ZHANGZHOU CITY,
FUJIAN PROVINCE, CHINA.



Thunder Sky Winston

产品合格证 QUALITY CERTIFICATE

型號規格
SPECIFICATION

TSWB-LYP100AHA

出廠編號
PRODUCT NUMBER

00019

檢驗員
CHECKER



檢測日期
CHECK DATE

20240926

結論：檢驗結果符合該產品技術要求
CONCLUSION: The product is qualified to its standard.



雷天温斯顿電池
THUNDER SKY WINSTON BATTERY