



EN Instruction for use

DE Gebrauchsanweisung

PL Instrukcja użytkowania

RU Инструкция по применению

RO Instrucțiuni de utilizare

UA Інструкція для користування

CZ Návod k použití

SK Návod na použitie

HU Használati utasítás

LT Naudojimo instrukcija

support.rawpol.com for other languages

LV	EE	BY	MD	BG	SI	ES	AT	NL	FR	DA	PT	IT	SE	FI	NO	TR	GR
PRODUCT NAME:																	
Protective clothing																	
Schutzkleidung																	
Odzież ochronna																	
Одежда защитная																	
Îmbrăcăminte de protecție																	
Standards																	
EN ISO 13688:2013 EN ISO 12947-2:2016																	
RS22301:2018 RS22302:2018																	

Only for the minimal risks - Nur für minimale Risiken - Только до минимальных загрозен - Исключительно для минимальных угроз - Doar pentru pericolile minime - Включено для рискованности в умовах мінімального ризику - Pouze pro minimální ohrožení - Iba pre minimálne ohroženia - Csak minimális veszélyforrásra - Tik esant minimaliems pavojams - RAW-POL, 96-200 Jawianów, 50, Polska



The member of REIS GROUP

v.B.C1LR.104

Sie sich unbedingt mit der Person kontaktieren, die Ihnen die Anleitung zur Verfügung gestellt hat oder mit dem Hersteller oder ermächtigten Vertreter des Herstellers, um ein Dokument für die Produktpartie zu erhalten, das Sie auch besitzten. Sie sollten unbedingt prüfen, ob Sie die aktuelle/richtige Gebrauchsanleitung für das vorliegende Produkt haben. Sollte die Anleitung nicht aktuell oder für das betreffende Produkt nicht geeignet sein, so muss unbedingt die aktuelle/richtige Gebrauchsanleitung beschaffen werden. Sie sollten sich mit ihrem Inhalt vertraut machen. **Beginnen Sie die Arbeit nicht, ohne sich vorher mit der aktuellen/richtigen Gebrauchsanleitung vertraut zu machen!**

DIESE ANLEITUNG LÄSST SICH MEHRMALIS VERVIELFALTIGEN, DAMIT SICH JEDER PRODUKTBENUTZER MIT IHR VERTRAUT MACHEN KANN. Im Falle jedweder Zweifel ist die Arbeitschutzfachkraft, Hersteller oder bevollmächtigter Herstellervertreter zwecks Klärung zu kontaktieren.

Erklärung der verwendeten Symbole: CODE = Warencode des Produkts, NUMBER = Artikelnummer, SIZES = verfügbare Größen, COLOURS = verfügbare Farben, PACKING = Anzahl der Produkte in der Identifikationsverpackung, STANDARDS = Normen (B = Produktlinie, [L] = Chargennummer, [D] = Produktionsdatum, [P] = REIS) = Identifikationszeichen des Herstellers, [I] = machen Sie sich mit der Gebrauchsanleitung vertraut, [O] = online-Anleitung, C = Konformitätszeichen, [R] = Zollunion-Konformitätszeichen, G = das Konformitätszeichen von Ukraine, B = Großbritanien Konformitätszeichen

[P] - Piktogramm von Raw-Pol, das bedeutet, dass das Außenmaterial, das die Sichtbarkeit und / oder das Material reflektierender Bänder gewährleistet, die Anforderungen von EN ISO 20471:2013 + A1:2016 (6.1, 6.2) erfüllt. Diese Anleitung gilt als fester Bestandteil der Verpackung und zugleich als Ihre Kennzeichnung. Gemäß der Verordnung (EU) 2016/425 Des Europäischen Parlaments und des Rates R17 Ziff. 1 müssen alle Kennzeichnungen nicht auf dem Produkt angebracht werden. Die Beschreibung der Kennzeichnung in der Anleitung gilt als eine bindende Information, auch dann, wenn Faktoren eintreten, die dazu führen, dass die Kennzeichnungen auf dem Produkt unleserlich sind. Sämtliche Kennzeichnungen, die in dieser Anleitung nicht erläutert wurden, beziehen sich direkt oder indirekt auf die Sicherheit und Gesundheit. Dieses Produkt und ihre Verpackung sind gemäß den geltenden lokalen Vorschriften zu entsorgen. Informationen hinsichtlich der Zusammensetzung des Produkts und seiner Verpackung sind auf der Website rawpol.com erhältlich.

PL INSTRUKCJA I INFORMACJE DLA UŻYTKOWNIKÓW
Producent: RAW-POL STEFAŃSKI SPÓŁKA JAWNA, Julianów 50, 96-200 Rawa Maz. / Polska.
Ten produkt należy do środków ochrony indywidualnej (SOI) określonych w Rozporządzeniu Parlamentu Europejskiego i Rady (UE) 2016/425 i spełnia wytyczne tego rozporządzenia. Zaklasyfikowany został do kategorii I – tylko do minimalnych zagrożeń.
Produkt/opis: Odzież ochronna. Szczegółową charakterystykę produktu podano na rawpol.com
Standardy: EN ISO 13688:2013 „Odzież ochronna. Wymagania ogólne”; EN ISO 12947-2:2016 „Tekstylia. Wyznaczenie odporności płaskich wyrobów na ścieranie metodą Martindale’a. Część 2: Wyznaczenie zniszczenia próbki roboczej”; passy obdaskowe: EN ISO 20471:2013 + A1:2016 (6.1, 6.2) „Odzież o intensywniej widzialności. Metody badania i wymagania”; Wewnętrzna specyfikacja techniczna producenta: RS22301:2018, RS22302:2018.
Przeznaczenie: Produkt ten jest środkiem ochrony indywidualnej mającym chronić użytkowników przed minimalnymi zagrożeniami, takimi jak: powierzchnie urazy mechaniczne, które nie wymagają pomocy medycznej np. zadrapania będące rezultatem uderzenia w twardo przeszły lub powstałe podczas zajmowania się ogrodnictwem; kontakt z gozycami powierzchniami o temperaturze nieprzekraczającej 50°C (czas ekspozycji na kontakt z gozycami powierzchniami podczas badania wynosił 30 sekund). Odzież zapewniająca widzialność w nocy lub północy w oświetleniu światła (zgodnie z załącznikiem A do Normy EN ISO 20471) przeznaczona do użycia w środowisku, gdzie widzialność użytkownika jest pożądana, ale w którym nie ma zagrożenia ze strony pojazdów lub innego zmechanizowanego sprzętu obsługiwanego przez operatorów, którego skutkiem mogły by być urazy inne niż powierzchniowe urazy mechaniczne. Uwaga! Odzież ta jest odzieżą o intensywniej czy zwiększonej widzialności. W zależności od środowiska pracy należy rozważyć, aby używać komplet odzieży tj. spodnie z pasami obdaskowymi wraz z kurtką z pasami obdaskowymi. Poziom ochronny pasek załączony na podstawie badań przeprowadzonych zgodnie z warunkami opisanymi w normach / specyfikacjach, których dotyczy. Produkt zapewnia ochronę przed wyżej wymienionymi zagrożeniami i jest przeznaczony do użycia w środowiskach, w których one występują. Zawsze należy przeprowadzić ocenę zagrożenia w danym środowisku pracy, aby na weryfikacji czy dany produkt zapewnia ochronę przed wszystkimi zagrożeniami występującymi w tym środowisku.

Ograniczenia: Nie należy stosować produktu niezgodnie z przeznaczeniem, zaleceniami instrukcji, w warunkach średniego i dużego ryzyka (dla którego właściwe jest stosowanie środków ochrony indywidualnej kategorii II oraz III) oraz gdy rodzaj wykonywanej pracy związany jest z ryzykiem zachcenia produktu o poruszające się obiekty np. ruchome części maszyn, które wiąże się z zagrożeniem dla zdrowia lub bezpieczeństwa. Produkt nie chroni części ciała, których nie osłania. Odzież nie jest przeznaczona dla aktywnych i ruchomych użytkowników ruchu drogowego. Ochrona przed zagrożeniami i niebezpieczeństwami niewymienionymi w instrukcji nie jest gwarantowana.
Użytkowanie i obsługa: Od osobistej odpowiedzialności użytkownika zależy zagwarantowanie funkcji ochronnej produktu. Produkt należy do noszenia. Produkt należy założyć na siebie. Jeśli produkt posiada jakiegokolwiek zapinacze, należy je zapinąć/zasunąć. Jeśli produkt zawiera elementy do zawiązania, należy je zawiązać. Należy zwrócić uwagę, aby produkt leżał wygodnie i dawał swobodę ruchów (w tym celu należy dopasować wszelkiego rodzaju regulacje, jeśli występują). W celu zjedną produktu należy najpierw rozpiąć/odczepić wszelkie wewnętrzne zapinacze/zapięcia oraz odłączyć wewnętrzne związane elementy, jeśli występują. W celu zapewnienia optymalnej ochrony produktu należy nosić zawsze zapinacze, utrzymując go w czystości oraz nie należy ograniczać widoczności powierzchni produktu poprzez jego zakrywanie. Widzialność produktu może zostać zmniejszona w przypadku niewłaściwego zczyszczenia albo modyfikacji produktu. Produkt trwale wyblakły czy trwale zabrudzony należy wymienić. Podczas noszenia passy obdaskowe muszą znajdować się na zewnątrz. Jeżeli produkt noszony jest razem z innymi środkami ochrony indywidualnej, należy uważać na to, aby były zagwarantowane łączne funkcje ochronne w zależności od przeznaczenia. W każdym przypadku wymogi mają pierwszeństwo. Przed użyciem użytkownik sprawdzi na własną odpowiedzialność, czy produkt nadaje się do przewidzianych czynności i obszczeń, jest kompletny, czysty, nie wyblakły i czy zagwarantowane są wszystkie funkcje ochronne. Należy sprawdzić go pod kątem uszkodzeń, które mogłyby mieć negatywny wpływ na funkcje ochronne (np. pęknięcia, dziury, rozwarzone szwy, uszkodzone zapięcia, warte pasy obdaskowe). Jeżeli zaistnieją takie negatywne wpływy, przed użyciem należy przywrócić pierwotny prawidłowy stan produktu (w tym celu należy skontaktować się z producentem bądź uprawnionym przedstawicielem producenta), a jeśli nie jest to możliwe, trzeba go wymienić. Podczas pracy także należy zwracać uwagę na zachowanie funkcji ochronnych. Utrata właściwości ochronnych oznacza, iż produkt został zużyty. Nie należy używać uszkodzonego bądź zużytego produktu. Produkt nie posiada dodatkowego wyposażenia oraz części zamiennych. Wyjątek stanowią spodnie z kieszeniami na ochraniacze kolan. Spodnie tego typu mogą być stosowane z ochraniaczami kolan OKNINGBEE, ONDUMBLEDOR oraz innymi o takich samych parametrach. Instrukcja używania ochraniaczy kolan:

- Złóż ochraniacz, wsunąć go w kieszeń zgodnie z oznaczeniem na ochraniaczu, a następnie rozłóż go tak, aby dobrze przylegał do kolana.
 - Jeśli kieszeń posiada zapinacze np. rzep, należy najpierw je odpiąć, a po umieszczeniu ochraniacza należy je zapinąć.
 - W celu użycia ochraniacza należy odpiąć zapinacze (jeśli występują), złóż ochraniacz i wsunąć go w kieszeń.
- Przeznaczenie:** Produkt należy przechowywać w odpowiedniej temperaturze, w suchym, dobrane wentylowanym miejscu. Zbyt duża wilgotność powietrza, zbyt wysoka lub niska temperatura lub intensywne światło mogą niekorzystnie wpłynąć na produkt. Producent nie bierze odpowiedzialności za jakość produktu przechowywanego niezgodnie z zaleceniami. Może to spowodować obniżenie poziomu ochrony produktu.

Wyprodukowano: Zaleca się dystrybuację (w tym transport) tego produktu w opakowaniu z kartonu lub folii. Zaledunkiem, przewozić i rozładunek powinny odbywać się w warunkach zabezpieczających przed zamoczeniem, zabrudzeniem i uszkodzeniem.

EN INSTRUCTION AND INFORMATION FOR THE USERS STANDARD

Manufacturer: RAW-POL STEFAŃSKI SPÓŁKA JAWNA, Julianów 50, 96-200 Rawa Maz. / Poland.

This product belongs to the Personal Protective Equipment (PPE), defined in the Regulation (EU) 2016/425 of the European Parliament and of the Council of April 26, 2016 on the approximation of the laws, regulations, administrative provisions and standards in the field of personal protective equipment. It is classified to category I, only for the minimal risks.

Product/description: Protective clothing. Detailed characterisation of the product is provided in rawpol.com.
Standards: EN ISO 13688:2013 „Protective clothing. General requirements”; EN ISO 12947-2:2016 „Textiles. Determination of the abrasion resistance of fabrics by the Martindale method. Part 2: Determination of specimen break down”; reflective bands: EN ISO 20471:2013 + A1:2016 (6.1, 6.2) „High visibility clothing. Test methods and requirements”; Internal technical specification of the manufacturer: RS22301:2018, RS22302:2018.

Intended use: Protection against the following minimal risks: superficial mechanical injury that do not need medical attention, e.g. scratches resulting from contact with objects and particles and particles and particles. The use of the product is intended for use to the contact with hot surfaces during the test was 30 seconds. Visibility clothing at night or twilight in the lighting of lights (in accordance with Annex A to EN ISO 20471) intended for use in an environment where user visibility is desirable but where there is no risk from vehicles or other mechanized equipment operated by operators that could result in other injuries than superficial mechanical risks. Warning! Clothing is not clothing with enhanced or high visibility. Depending on the working environment, considering using a set of clothing, i.e. trousers with reflective stripes together with a jacket with reflective stripes. The level of protection was obtained on the basis of tests carried out according to conditions described in the norms / specifications to which they apply. The product provides protection against the above risks and it is intended for use in the environments in which they occur. Please always carry out a risk assessment in a given work environment to verify whether the product provides protection against all risks available in this environment.

Restrictions: Do not use the product other than in accordance with the intended purpose, recommendations in the instruction, in average conditions and high-risk (for which it is appropriate to apply measures to protect individual category I and II) and when the type of work is related to the risk of the product being caught up by moving objects, e.g. moving parts of machines and such PPE being caught is associated with a health or safety hazard. This product does not protect parts of the body, which it does not cover. Clothing is not intended for active and passive road users. Protection against risks and dangers not mentioned in the instructions is not guaranteed.
Use and operation: The personal liability of the user is determined by the way the product is used. The product is intended to be worn. This product must be put on the body. If the product has any fasteners, they need to be fastened/ zipped. If the product has components to tie, they need to be tied. It should be noted that the product lies comfortably and gives freedom of movement (to do this, match all kinds of adjustments, if any). In order to remove the product, first unfasten/unzip all previously fastened/zipped elements and untie previously tied elements, if any. In order to assure optimal protection of the product, it must be worn always buttoned up, kept clean and do not restrict visibility of the product through covering. Visibility of the product can be reduced in the case of improper cleaning or modification of the product. The product permanently disclosed or permanently soiled must be replaced. While wearing, the reflective belts must be on the outside. If the product is worn together with other means of personal protection, total protection features must be guaranteed depending on the purpose. In any case the requirements take precedence. Before using, the user checks on his/her own responsibility, whether the product is suitable for working activities, is complete, clean, not faded, and whether all functions are guaranteed. Check the damages, whether they could have a negative impact on the safety functions (e.g. cracks, holes, ripped seams, broken prongs, worn reflective belts). If there is such a negative impact, before using, restore the original valid status of the product (to do this, contact the manufacturer or the authorised representative of the manufacturer), and if this is not possible, replace it. While working, pay attention to the fact that the product is not damaged or worn out. The product that the product has been worn. Do not use a damaged or worn out product. The product does not have additional equipment and spare parts. The exception are trousers with knee protector pockets. Trousers of this type can be used with OKNINGBEE, ONDUMBLE-DOR knee protectors and other with the same parameters. Instruction for use of knee protectors:

- Hold the knee protector, insert it into the pocket in accordance with the mark on the knee protector, and then spread it in order to adhere well to the knee.
- If the pocket has a fastener e.g. Velcro, first unclip it and after placing the knee protector, it should be fastened.
- To bring the knee protector out, open the fastener (if present), fold the knee protector and pull it out of the pocket.

Before using the knee protectors, read the instruction of use for knee protectors.

Materials used to made the product, should not adversely affect the user's hygiene or health. However, any substance contained in the material of the product or being a component of the product can be allergen, such as cotton, leather, metal parts, latex, stains, etc. It is recommended that sensitive persons test the product or seek for medical advice before use.

Size: The product should be of sufficient size, which must be adjusted before starting operation. The product size is provided directly on the product or on internal label or on packaging. Available size range is specified in the field SIZES. Full size range is provided in the tables available on rawpol.com.

Cleaning, maintenance and disinfection: Recommendations for maintenance, cleaning are provided on the label of the product. It is recommended to use generally commercially available cleaners, preservatives for each type of material, which does not have negative impact on the user's body. The products, which do not have sew-in in the maintenance, cleaning label, must only be cleaned with damp, soft cloth, dry flat. It is not recommended to use any additional methods for disinfection and disinfectants, as this may have impact on reducing levels of protection.

The pictograms for maintenance, cleaning, which can be applied, along with an explanation.
☞ – Hand wash, max 40°C, ☞ – Wash in temp. to 30°C, ☞ – Wash in temp. to 40°C, ☞ – Wash in temp. to 95°C, ☞ – Do not bleach / chlorine, ☞ – Do not tumble dry, ☞ – Ironing temperature 200°C, ☞ – Ironing temperature 150°C, ☞ – Ironing temperature 110°C, ☞ – Do not iron, ☞ – Do not dry clean, 25 x – max. number of wash cycles for items of clothing which meets requirements of EN ISO 20471 (clauses/points of standard).

The specified maximum number of cleaning cycles is not the only factor affecting shelf life of the clothing. The shelf life is also dependent on using, storage, etc.

Storage: The product should be stored at the appropriate temperature, in dry and well ventilated place. Too high humidity of air, too high or low temperature or intense light can adversely impact the product quality. Manufacturer accepts no liability for the quality of the product stored contrary to the instructions. This may result in a lowering of the product protection level.

Type of packaging: It is recommended to distribute (including transport) the product in the package with cardboard or plastic film.

Loading, transport and unloading should take place in environment protecting against splashes, dirt and damage.

Product durability can be estimated on the basis of the product wear and tear. Considering various use intensities and environmental factors, such as sunlight, rain, etc. it is not possible to provide a precise span. The product retains its protective properties up to the moment of a damage which cannot be repaired without decreasing its protective level. Occurrence of mechanical damages means that the product should be repaired or immediately withdrawn from use. With proper warehousing the storage time of the product can be up to 7 years from the date of production (in the case of clothing containing polyurethane up to 5 years). This period may be extended by performing the appropriate tests.

Date of manufacture is indicated on the packaging or the product. This is with the batch number, e.g. 290120191234; explanation: The third and fourth digits indicate month of manufacturing, and the subsequent four digits identify year of manufacturing. Other digits together with the above identify the number of batch.

The access to the EU declaration of conformity can be accessed at support.rawpol.com.

In the event that this manual is out-of-date because of changes in law or other factors, download the new version. Current instructions are available on the rawpol.com or support.rawpol.com. This manual is marked with version v.B.C1LR.104, where B.C1LR is the identifier of product group and 104 the subsequent version number. Before starting operation, verify having current/appropriate operation manual for the product, read this manual carefully and keep it for duration of the use of protection. If the labels explained herein are not the same as labels on the product, this means that the manufacturer has changed the marking on the product. In this case, it is essential to contact the person who made the manual available, or contact the manufacturer or the authorized representative of the manufacturer, in order to obtain a document to the batch, which you have. It is essential to verify having current/appropriate manual for the possessed product. If the manual is out-of-date or inappropriate to the batch, it is essential to obtain current/appropriate manual and refer to its contents. **Do not start operation without reading information included in the current/ correct operation manual!** THIS MANUAL CAN BE REPEATEDLY COPIED IN ORDER ANY USER CAN READ THE INFORMATION INCLUDED HEREIN. In any case please contact with safety expert, the manufacturer or the authorized representative of the manufacturer in order to explain them.

Explanation of used symbols: CODE – commodity product code, NUMBER – article number, SIZES – available sizes, COLOURS – available colour range, PACKING – quantity of the product in the smallest packaging/ quantity in the carton, STANDARDS – standards (B – product line, [L] – batch code, [D] – date of manufacture, [P] = REIS) – manufacturer's identification mark, [I] – refer to the operational manual, [O] – online instruction, C = conformity mark, [R] – conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

ments of EN ISO 20471:2013 + A1:2016 (6.1, 6.2)

[I] - make the user familiar with the product, [O] - online instruction, C = conformity mark, [R] - conformity sign of the Customs Union, G – ukrainian conformity sign, G – Great Britain conformity sign

[P] - Raw-Pol company pictogram, meaning that outside fabric ensuring visibility and/or the fabric of reflective bands must require-

