


# MST Phaco Tip... Tips

## Preparing Your Silicone Sleeve



Injecting a small amount of OVD into the sleeve end reduces the chance of tearing


## How To Help Your Wrench Last



Partially seated wrenches can cause wrenches to strip  
Fully seated wrenches reduce the chance of stripping

## Experience Our Design Advantages

### MST Phaco Tips and Sleeves



Our phaco tips and sleeves are designed to form a seal so that irrigation fluid only comes out of its intended ports


### Ordinary Phaco Tips and Sleeves




Ordinary phaco tips and sleeves leave a gap for irrigation fluid to flow, which can push pieces forward




We design MST phaco tips to provide full vacuum holding



Leaks reduce holding power



Now You See It  
MST sleeves are designed to enable you to see structures underneath them



Now You Don't  
Others block your view...