

Cessna 172S

SUPPLEMENT NO.

Vaccine Scattering

Registration No.	OK - ELU
Serial No.	172S9329

This supplement supplies the information necessary for the efficient operation of the airplane when the Vaccine Scattering is installed. The information contained within this supplement is to be used in conjunction with the complete AFM.
This supplement is a permanent part of this AFM and must remain in this AFM at all times when the Vaccine Scattering is installed.

Revision No. NZ AE/160-DLP1 to AFM Supplement 172S, is approved under the authority of DOA ref. EASA.21J.094

Approved (CVE): Ing. Miroslav Mikel

Date : 20. 08. 2015

August 20/15

NZ AE/160-DLP1

1/4

LOG OF APPROVED SUPPLEMENTS

SUPP. NO.

SUPPLEMENT NAME

REVISION LEVEL
EQUIPMENT INSTALLED

Vaccine Scattering

27

Revision No. NZ AE/160-DLP1 to AFM Supplement 172S, is approved under the authority of DOA ref. EASA.21J.094

Approved (CVE): Ing. Miroslav Mikel

Date : 20. 08. 2015

August 20/15

NZ AE/160-DLP1

1/2

ELMONTEK a. s.
Vratimovská 69/335
718 00 Ostrava - Kunčičky
DIČ: CZ47155086

CONFORM CU ORIGINALUL

LOG OF REVISION

Rev. No.	Revised Pages	Description of Revision	CAA Approved	Date

Intentionally left blank

ELMONTEX a.s.
Vratimovská 69/335
718 00 Ostrava - Kunčičky
DIČ: CZ45153086

CONFORM CU ORIGINALUL

**PILOTS OPERATING HANDBOOK
SUPPLEMENT**

Vaccine Scattering

**SECTION 1
GENERAL - Not Affected**

**SECTION 2
LIMITATIONS**

If the the dropping equipment is installed, the aeroplane must be operated in the **NORMAL CATEGORY** only.
The speed is to be kept between 80 -105 KIAS during the vaccine application process.
It is required that except for the pilot the dropping equipment operator is on board of the plane as well.

**SECTION 3
EMERGENCY PROCEDURES - Not Affected**

**SECTION 4
NORMAL PROCEDURES - Not Affected**

**SECTION 5
PERFORMANCE - Not Affected**

**SECTION 6
WEIGHT & BALANCE/EQUIPMENT LIST - Not Affected**

**SECTION 7
AIRPLANE & SYSTEMS DESCRIPTIONS**

The dropping equipment for rabies vaccine scattering is installed. The dropping equipment operator sits on the right seat rotated backwards during takeoff and landing. The operator's seat belts shall be fastened.

August 20/15 **NZ AE/160-DLP1** 3/4

ELMONTEX a. s.

Vratimovská 69/335
718 00 Ostrava - Kunčický
DIČ: CZ47155086

CONFORM CU ORIGINALUL

Vaccine Scattering

**PILOT'S OPERATING HANDBOOK
SUPPLEMENT**


The engine power setting – as required to keep the horizontal flight.
The dropping equipment operator does not have to be fastened by
seat belts during the dropping equipment operation.

**SECTION 8
AIRPLANE HANDLING, SERVICE & MAINTENANCE
- Not Affected**

**SECTION 9
SUPPLEMENTS**

Issued Vaccine Scattering supplement.

ELMONTEX a.s.
Vratimovská 69/335
718 00 Ostrava-Kunčický
DIČ: CZ47155089



4/4

NZ AE/160-DLP1

August 20/15

CONFORM CU ORIGINALUL