


MST Phaco Tip... Tips

Preparing Your Silicone Sleeve



Injecting a small amount of OVD into the sleeve end reduces the chance of tearing

How To Help Your Wrench Last




Partially seated wrenches can cause wrenches to strip

Fully seated wrenches reduce the chance of stripping

Experience Our Design Advantages

MST Phaco Tips and Sleeves



Our phaco tips and sleeves are designed to form a seal so that irrigation fluid only comes out of its intended ports


Ordinary Phaco Tips and Sleeves




Ordinary phaco tips and sleeves leave a gap for irrigation fluid to flow, which can push pieces forward



We design MST phaco tips to provide full vacuum holding




Leaks reduce holding power



Now You See It

MST sleeves are designed to enable you to see structures underneath them



Now You Don't

Others block your view...