



Explicatia incaperilor la cota 0.000

No	Denumirea incaperii	Suprafata ml
1	Tambur	14.36
2	Vestibul (sala de asteptare)	42.87
3	Tambur	3.4
4	Cafeaua (20 locuri)	131.69
5	Tambur	4.98
6	Tambur	17.13
7	Lavaor cafe	1.59
7'	Wc cafe	2.03
8	Lavaor personal	1.71
8'	Wc personal	2.07
9	Incaperi tehnica	10.27
10	Hol	6.03
11	Coridor	3.12
12	Depozit produse uscate	10.1
13	Incaperi tablouri electrice	5.52
14	Incaperi personal	11.1
15	Hol	6.12
16	Punct medical	11.45
17	Tambur	7.39
18	Sala asteptare	105.71
19	Tambur	3.4
20	Birou	21.26
21	Banca	21.05
22	Incaperi auxiliara	4.71
23	Hol	23.8
24	Casa scarii	23.32
25	Vestibul	42.87
26	Tambur	14.36
27	Tambur	3.4
28	Post politie de frontiera	7.96
29	Sala verificare	206.9
30	Tambur	3.4
31	Lavaor femei	5.99
31'	Wc femei	2.21
31''	Wc femei	1.78
32	Lavaor barbati	5.4
32'	Wc barbati	1.78
32''	Wc barbati	1.78
33	Wc persoane cu dizabilitati Camera mana si a copilului	10.33
34	Sala depozitara temporara bagaje intrare	17.57
35	Sala depozitara temporara bagaje iesire	9.43
36	Incaperi verificare personala	9.43
37	Incaperi tura	13.32
38	Tambur	3.4
39	Post politie de frontiera	7.96
40	Sala asteptare	206.9
41	Wc persoane cu dizabilitati Camera mana si a copilului	10.99
42	Lavaor barbati	6.07
42'	Wc barbati	1.78
42''	Wc barbati	1.78
43	Lavaor femei	2.63
43'	Wc femei	1.78
43''	Wc femei	2.21
44	Tambur	7.23
Suprafata totala la cota 0.000		1106.8200

Beneficiar: Serviciul Vamal al RM		15870-AC		
		Reabilitarea si modernizarea punctului de trecere a frontierei Sculei din Republica Moldova de la frontiera moldo-romana.		
Schimb. Nr. part. Plansa Nr. doc. Semnatura Data		Cladirea administrativa a postului vamal (poz 1).	Faza PE	Plansa 4
Sp. princ. Mihailov A Executat Mihailov A		Plan la cota 0.000		
		07.18 07.18	INCP mun. Chisinau	

Et. Tite
 Tit. e adob
 Act. eia