



Compliance Report

Applicant: GUANGZHOU TOPMEDI COMPANY LIMITED
Address: RM1505-1507, Golden Sky Tower, No.83, Middle Huadi Road,
Liwan Dist, Guangzhou, China.

Product: Electric Hospital Bed, Electric Wheelchair,
Manual Wheelchair, Manual Hospital Bed,
Walking Aids, Shower Chair, Commode Chair
Type: See annex for details

Product Classification: Class I

The submitted technical files including test report of the above products have been reviewed against the self declaration requirements of conformity for CE marking according to Annex I & VII of the 93/42/EEC Medical Device Directive (including 2007/47/EC).

The review result of the technical files and test report support the self declaration for the devices listed above. The test report and the technical files are the annex of this report and should be used together.

Where the manufacturer affix's the CE marking to the product listed they must ensure that all the requirements of the appropriate EU directive(s) have and continue to be met.

This report is not a certificate of conformity.

No. 02515

Initial Issue Date: 25 Apr 2016

A handwritten signature in blue ink that reads 'Tony Chen'. The signature is written in a cursive, flowing style. Below the signature is a horizontal line.

Tony Chen

General Manager (Signature)



Annex to Report (No. 02515)

GUANGZHOU TOPMEDI COMPANY LIMITED

Product Name	Type
Electric Hospital Bed	THB3241WGZF7, THB3240WZF8, THB3242WGZF8, THB3239WZF4, THB3238WGZF4, THB3133WBF6, THB3230WZ, THB3238W, THB3233WG, THB3222WB, THB3236W, THB3230W, THB3220W, THB3243LWMF10, THB3244WM, THB3236WM, THB3246WM, THB3230WMGF3, THB3120WMB, THB3237WMF3, THB3231WM, THB3220MF2, THB3230WMGZ, THB3201, THB3202, THB3203, THB3204, THB3205, THB3026
Electric Wheelchair	TEW139, TEW131, TEW121LF1, TEW129, TEW124, TEW105L, TEW106L, TEW107LAEPF1, TEW108LA, TEW110LAE, TEW102LAEPF1, TEW110LF1, TEW110LAEF2, TEW123, TEW125GC, TEW123GC, TEW123F1, TEW101A, TEW110A, TEW121, TEW112, TEW122LGC, TEW120AG, TEW127, TEW141, TEW128, TEW140, TM-EW-015, TM-EW-016, TM-EW-017, TM-EW-021, TM-EW-028, TEW007A, TEW007, TEW806C, TEW-CK05, TEW001, TEW002, TEW003, TEW004, TEW005, TEW006, TEW007, TEW008, TEW009, TEW010, THE130F1, THE130, THE5777

This annex is only valid if attached to the report mentioned above.



Annex to Report (No. 02515)

GUANGZHOU TOPMEDI COMPANY LIMITED

Product Name	Type
Manual Wheelchair	TAW205LHQ, TAW251LHPQ, TAW250LCPQ, TAW253LACHQ, TAW218LQ, TAW959LQ, TAW957LQ, TAW955L, TAW950BEF1, TAW950LBPQ, TAW980LA, TAW952LCQ, TAW953LB, TAW208LAP, TAW207LABP, TAW908LJ, TAW907LABH, TAW903LQ, TAW874LJF5, TAW983L, TAW974LP, TAW864L, TAW874LAH, TAW864LAJ, TAW870LAJ, TAW869LJ, TAW878LAJ, TAW870LABJF5, TAW879LAJ, TAW872LAJ, TAW873LABJP, TAW868L, TAW871LBJ, TAW863LABJ, TAW805LABJ, TAW976LABJF2-43, TAW976LAB, TAW804LABJP, TAW800LBJ, TAW803LB, TAW807LABP, TAW980LA-30, TAW908LAF17, TAW874LAJ-30, TAW980LA-35, TAW809L, TAW818LB, TAW001, TAW002, TAW003, TAW004, TAW005, TAW006, TAW007, TAW008, TAW009, TAW010, TLS737LQ-36, TLS734LQ-36, TLS731LQ-36, TLS730LQ-36, TLS732LQ-36, TLS727LQ-36, TLS720LQ-36, TLS723LQF1-36, TLS723LQ-36, TLS721LQ-36, TLS722LQ-36, TLS770LQ-32, TLS771LQ-32, TLS779LQ-36, TLS777LQ-36, TLS778LQ-36, TLS717L-30, TLS710L-30, TLS786LQ-36, TLS785LQ-36, TLS740LQ-36, TLS766LQ-36, TLS755LQ-36, TLS735LQ-36, TLS744LQ-43, TLS756LQ-36, TLS701, TLS702, TLS703, TLS704, TLS705, TLS706, TSW908AQ, TSW909, TSW909B, TSW902C, TSW901B, TSW901, TSW975-51, TSW907BC, TSW972BF2, TSW903, TSW904B, TSW972, TSW972B, TSW976ABJ-43, TSW951B-56, TSW209AE-61, TSW210ABE-61, TSW874F5, TSW870ABJ, TSW802-35, TSW810Y, TSW809, TSW809B, TSW874A, TSW874, TSW873, TSW869X, TSW875, TSW868, TEW-CK06, TRW258LBYGP, TRW958LBCGPY, TRW985LBGY, TRW954LGC, TRW203BJ, TRW204BJ, TRW212CEG, TRW801G, TRW954GC-46, TRW902GC-46, TRW901, TRW902, TRW903, TRW904, TRW905, TRW906, THE778LQ-36, THE779LQ-36, THE736LQ, THE255LPQ, THE004LGCP, THE958LBCGPY-38, THE974LAH-46, THE869LJP-43, THE874LAHP, THE018LPQ, THE870LAHP, THE976LA, THE203L, THE001, THE002, THE003, THE004, THE005

This annex is only valid if attached to the report mentioned above.



Annex to Report (No. 02515)

GUANGZHOU TOPMEDI COMPANY LIMITED

Product Name	Type
Manual Hospital Bed	THB3030W, THB3026WG, THB3023W, THB3020W, THB3050W, THB3012W, THB3131, THB3121, THB3132, THB3221W, THB3021SF2, THB3000, TRA3080W, TRA532, TRA533, TRA534, TRA535, TRA5311, TRA579, TRA570, TRA531, TRA564, TRA574, THB3001, THB3002, THB3003, THB3004, THB3005, THB3006
Shower Chair	TBB7962L, TB7992LU, TBB7991L, TBB799L, TBB7985L, TBB798L, TBB796L, TBB7982L, TBB7984LA, TBB7981L, TBB7986L, TBB797L, TBB790, TBB7971L, TBB7963L, TBB7972L, TBB7920L, TBB568S, TBB569S, TBB792, TBB790B, TBB795, TBB7933S, TBB791S, TBB7931, TBB794L-1, TBB794L, TBB793S, TBB7923L, TBB7901, TBB7902, TBB7903, TBB7904, TBB7905, TBB7906
Commode Chair	TCM654LGCU, TCM609GCU, TCM619GC, TCM609GCJ, TCM609GCUF1, TCM683L, TCM681, TCM609LU, TCM609BU, TCM609U, TCM697S-1, TCM697S, TCM695S, TCM699L, TCM693, TCM691S, TCM694S, TCM691, TCM692, TCM8831L, TCM696, TCM8921, TCM892, TCM883L, TCM893L, TCM893, TCM8931, TCM8962, TCM8832U, TCM894L, TCM895L, TCM8941, TCM894, TCM896, TCM813(S), TCM813, TCM813L, TCM8951L, TCM811, TCM8101, TCM810, TCM897, TCM898, TCM8995L, TCM8992L, TCM899, TCM8992, TCM897A, TCM890, TCM801, TCM802, TCM803, TCM803, TCM804, TCM805, TCM806

This annex is only valid if attached to the report mentioned above.



Annex to Report (No. 02515)

GUANGZHOU TOPMEDI COMPANY LIMITED

Product Name	Type
Walking Aids	TWA203, TWA201, TWA965LH, TWA966LH, TWA968L, TWA914H, TWA965LH-1, TWA9622, TWA9621, TWA969H, TWA9142L, TWA914L, TWA9123L, TWA961L, TWA9128L, TWA9126L, TWA9631L, TWA912L, TWA918L, TWA9125L, TWA917L(S/M/L), TWA9632L, TWA919L, TWA967L, TWA913L, TWA963L, TWA9131L, TWA915L, TWA9121L-A, TWA9122L, TWA912L(XS), TWA9124L, TWA962, TWA9145L, TWA960, TWA9600, TWA9610, TWA9612, TWA910L, TWA920L, TWA930L, TWA9301L, TWA929L, TWA939L, TWA9106L, TWA9206L, TWA9306L(14), TWA9306L, TWA948L, TWA949L, TWA9296L(15), TWA9203L, TWA9276L(12), TWA9276L(13), TWA927L, TWA9271L, TWA933L, TWA923L, TWA937L, TWA9204L, TWA938L(12), TWA928L, TWA9281L, TWA9280L, TWA927L-A(P7), TWA9272L, TWA930L(P1), TWA9301L(P13), TWA910L(1), TWA939L(2), TWA939L(4), TWA939L(8), TWA939L(9), TWA939L(10), TWA9202L, TWA9300L, TWA926, TWA946S, TWA932, TWA941, TWA942S, TWA9321, TWA945, TWA9322, TWA946A, TWA924, TWA921, TWA924L, TWA921L, TWA934, TWA931, TWA9212L, TWA931L, TWA947, TWA9111L, TWA911L, TWA943L, TWA945L, TWA940L, TWA9221, TWA9242L, TWA922, TWA925L(L/M/S), TWA935(L/M/S), TWA935S, TWA9252L, TWA925LA, TWA925LB, TWA583, TWA936L, TWA001, TWA002, TWA003, TWA004, TWA005, TWA006, TWA007, TWA008, TWA009, TWA010, THE965L, THE965LF1

This annex is only valid if attached to the report mentioned above.