

Listă planificată de reparare a imprimantelor, anul 2023.

Nr .	Model	Numele piesei de schimb	Pret p/u unitate	Cantitatea imprimantei	Reparații planificate	Descriere	U/m
1.	Canon LBP 3010, 6020, 6030	Profilaxia aparatului	120	195	La necesitate	Conform Anexei 2.	buc.
		Película termica	350				
		LFR(Presroll)	480				
		Busching	120				
		Roller	140				
		Plata	600				
2.	Canon IR 1133	Profilaxia aparatului	240	1			
		Película termica	480				
		LFR(Presroll)	580				
		Busching	220				
		Roller	140				
3.	Canon LBP 212DW, Canon MF 411DW, MF443dw, MF453dw, MFW 51939	Profilaxia aparatului	120	23			
		Película termica	480				
		LFR(Presroll)	580				
		Busching	220				
		Roller	120				
4.	Canon MFU4330D, MF4018, MF 4410, MF 4140, Canon MF 3010	Profilaxia aparatului	120	8			
		Película termica	350				
		LFR(Presroll)	480				
		Busching	220				

		Roller	120						
5.	Canon i-sensys MF 231	Profilaxiaaparaturului	120	1					
		Peliculatermica	350						
		LFR(Presroll)	480						
		Busching	220						
		Roller	120						
6.	CanonLaserBase MF 3110	Profilaxiaaparaturului	240	2					
		Peliculatermica	480						
		LFR(Presroll)	580						
		Busching	220						
		Roller	140						
7.	Canon MF 113W, HP M130a	Profilaxiaaparaturului	120	4					
		Peliculatermica	350						
		LFR(Presroll)	480						
		Busching	220						
		Roller	120						
8.	Canon MFU, HP MFD, Printer HP Laser,Printer Laser, Printer	Profilaxiaaparaturului	120	42					
		Peliculatermica	350						
		LFR(Presroll)	480						
		Busching	220						
		Roller	120						
9.	Canon IR 2520, Canon IR 2206	Profilaxiaaparaturului	240	3					
		Peliculatermica	500						
		LFR(Presroll)	500						
		Busching	240						
		Roller	180						

10.	HP P 2055	Profilaxiaaparaturului	120	10
		Peliculatermica	350	
		LFR(Presroll)	480	
		Busching	220	
		Roller	120	
11.	HP Laser M12a	Profilaxiaaparaturului	120	25
		Peliculatermica	350	
		LFR(Presroll)	480	
		Busching	150	
		Roller	120	
12.	Epson L1300, PrinterEpson	Roller	240	6
		Pick-uproller	250	

Suma totala (1buc) – 16470.00 lei