

Cessna 172S

SUPPLEMENT No.

Vaccine Scattering

Registration No.	OK - ELN
Serial No.	172S9346

This supplement supplies the information necessary for the efficient operation of the airplane when the Vaccine Scattering is installed. The information contained within this supplement is to be used in conjunction with the complete AFM.  
This supplement is a permanent part of this AFM and must remain in this AFM at all times when the Vaccine Scattering is installed.

Revision No. NZ AE/160-DLP1 to AFM Supplement 172S, is approved under the authority of DOA ref. EASA.21J.094

Approved (CVE): Ing. Miroslav Mikel

Date : 20. 08. 2017

August 20/17

NZ AE/160-DLP1

1/4

## LOG OF APPROVED SUPPLEMENTS

SUPP.  
NO.

SUPPLEMENT NAME

REVISION  
LEVEL

EQUIPMENT  
INSTALLED

Vaccine Scattering

7

Revision No. NZ AE/160-DLP1 to AFM Supplement 172S, is approved under the authority of DOA ref. EASA.21J.094

Approved (CVE): Ing. Miroslav Mikel

Date : 20. 08. 2015

August 20/17

NZ AE/160-DLP1

1/2

ELMONTEX

Vratimovská 69/338  
718 00 Ostrava - Krušovice  
DIČ: CZ47155086

CONFORM CU ORIGINALUL

## LOG OF REVISION

Rev. No.	Revised Pages	Description of Revision	CAA Approved	Date

Intentionally left blank

**ELMONTEX a. s.**  
Vratimovská 69/335  
718 00 Ostrava - Kunčičky  
DIČ: CZ47155086

CONFORM CU ORIGINALUL

SECTION 1  
GENERAL - Not Affected

SECTION 2  
LIMITATIONS

If the the dropping equipment is installed, the aeroplane must be operated in the NORMAL CATEGORY only.  
The speed is to be kept between 80 -105 KIAS during the vaccine application process.  
It is required that except for the pilot the dropping equipment operator is on board of the plane as well.

SECTION 3  
EMERGENCY PROCEDURES - Not Affected

SECTION 4  
NORMAL PROCEDURES - Not Affected

SECTION 5  
PERFORMANCE - Not Affected

SECTION 6  
WEIGHT & BALANCE/EQUIPMENT LIST - Not Affected

SECTION 7  
AIRPLANE & SYSTEMS DESCRIPTIONS

The dropping equipment for rabies vaccine scattering is installed.  
The dropping equipment operator sits on the right seat rotated backwards during takeoff and landing. The operator's seat belts shall be fastened.

**ELMONTIX** s.r.o.  
Vratimovská 69/335  
718 00 Ostrava - Křížcičky  
DIČ: CZ47155086

CONFORM CU ORIGINALUL

Vaccine Scattering

PILOT'S OPERATING HANDBOOK  
SUPPLEMENT

The engine power setting – as required to keep the horizontal flight.  
The dropping equipment operator does not have to be fastened by  
seat belts during the dropping equipment operation.

SECTION 8  
AIRPLANE HANDLING, SERVICE & MAINTENANCE  
- Not Affected

SECTION 9  
SUPPLEMENTS

Issued Vaccine Scattering supplement.

**ELMONTEX s.r.o.**  
Vratimovská 69/335  
718 00 Ostrava - Kuncířka  
DIČ: CZ47165086

4/4

NZ AE/160-DLP1

August 20/15

CONFORM CU ORIGINALUL