

Product change follow up

Document Date 16/02/2023

Date	Item	Reference*	Detail	Date of application	Informdis	Comment
31/01/2023	Biopsy/Suction connector for EG-580UR	WF-BAL-UR	Change luers to larger ones to avoid disconnections.	31/01/2023	-	
05/09/2022	FUJI 580 UT/UR SEPARATOR SET	WF-B580U	Improved blocker sealing	05/09/2022	-	
06/07/2022	Connectors O-ring sets	B3016-E B3016-O B3016-P B3016-F B3016-S B3016-N	The O-ring sets used with Soluscope connectors are updated. This update concerns also newly produced connectors. B3016-N has been created for Sonoscape Endoscope	06/07/2022	-	
21/06/2022	Biopsy/Suction connector for echo-bronchoscope	SL-S1-O-BFU	Exchange of biopsy and aspiration connectors for better ergonomics	21/06/2022	-	
15/03/2022	Biopsy/Suction connector for EG-580UT	WF-BAL-UT	Change luers to larger ones to avoid disconnections.	15/03/2022	-	
08/03/2022	Additional connector for Olympus	WO-S140	Stainless steel connector improvement	08/03/2022	-	
07/12/2021	All connectors	A3137 A3040	To improve connectors reliability, luer ref. A3137 and nut ref. A3040 are removed from all connectors. Concerned connectors are: WO-AW-UL WP-AW-UL WO-AW WTM-S WF-AW-530S2 WF-AW-L WH-AW-G7 WS-AW WO-AW190X WN-AW500 WP-AW-G1	07/12/2021	-	Except for the WTM-S which keeps 1 out of 5.
01/10/2020	Pentax A/W connection block	WP-AW2	The WP-AW2 connector replaces WP-AW for specific endoscopes. The list of endoscopes for which WP-AW2 applies is updated on https://pro.soluscope.com . This change enables improving the grip of the connector to the endoscope and water/air channel separation. For the listed endoscopes, it is not required to update your WP-AW connector if it does not show recurrent errors while used on the washer disinfectant and has followed maintenance recommendations detailed in Informdis 3-2016 document.	01/10/2020	-	
03/09/2020	Connectors O-ring sets	B3016-E B3016-O B3016-P B3016-F B3016-S	The O-ring sets used with Soluscope connectors are updated. This update concerns also newly produced connectors.	03/09/2020	-	

08/06/2020	Biopsy/Suction connector for Sonoscape 500 and 550	WN-BA500	A new connector is created to connect Sonoscape endoscopes: serie 500 and 550. This new connector ref.WN-BA550 replaces the connector ref. WN-BA500.	08/06/2020	-	
18/03/2019	Biopsy/Suction connector for Fuji 530US	WF-BAB-530US	To improve the connection to the endoscope, the biopsy connector (ref. W3058) has been replaced by the ref. A3142S.	18/03/2019	-	
12/02/2019	Biopsy/Suction Pentax connector	WP-BA	This reference is discontinued. It is replaced with the WP-BAS-L connector which includes a stainless steel Luer Lock to provide higher quality and reliability when connected to the endoscope.	12/02/2019	-	
03/07/2018	AS300 tube for Fujifilm Serie 700	HY-T-FU-10187	New tubes codes are released to connect serie 700 Fujifilm endoscope to the AS300 storage cabinet. Connectors look-up table reflects the change.	03/07/2018	-	
07/08/2017	Stainless Steel Luer Lock on Hooks-up	WS-2BA WO-BBAL WW-BA WS-BA WF-S WO-CO2 WS-BAX SL-W1-BBAL SL-S1-S SL-S1-S-2B SL-S1-W WW-4BA SL-S1-X	The stainless steel Luer lock connector used in the listed hooks-up has been replaced with a new rotating luer lock to facilitate the handling of the hook-up and reduce the risk of mis-connection to the endoscope.	04/08/2017	-	
06/06/2017	Blocker for Olympus endoscope	WO-B140	A change has been applied on the product to feature a new inox insertion base and improve mechanical reliability. The previous version is discontinued, the new part can be ordered with the same Reference code.	06/06/2017	-	
06/06/2017	Leak test connector for Olympus Endoscope	SL-TO-O-S SL-TO-O-UL	The leak test connector of these references has been improved to ensure adequate insertion of the connector in the endoscope. The screw used to calibrate the insertion diameter of the connector is replaced by a non adjustable part to always ensure the same insertion diameter in the endoscope.	06/06/2017	-	
06/06/2017	Leak test connector for FujiFilm endoscope	SL-TO-F SL-TO-F-UL	The leak test connector of these references has been redesigned to improve the handling of the product for plugging on Fujifilm endoscopes, particularly for Serie 700 "Eluxeo" generation. Change applies from batch 021981000.	06/06/2017	-	
20/01/2017	Connectors for FujiFilm EG-580UT and EG-580UR	WF-B580U WF-BAL-UR WF-BAL-UT	Changes on these connectors have been performed to improve fault-preventing when connected to the endoscope.	20/01/2017	-	-

02/11/2016	Leak test connector for FujiFilm endoscope	SL-TO-F	The SL-TO-F reference is updated for full compliance with new FujiFilm Serie 700 "Eluxeo" endoscope range. This new version is compliant with previous scope generation. It is identified as "F7" on the connector tube. Please note that previous generation identified as "F" may not be usable on Serie 700 endoscope. "F7" is available from batch 018137000.	02/11/2016	-	-
17/10/2016	Air/Water connector for Olympus Serie 140 to 190	WO-AW190S	The WO-AW190S reference is discontinued and replaced with the new WO-AW190X. The WO-AW190X features a new air/water connector with locking system on the endoscope air/water balloon connection system to facilitate the installation and reduce the risk of release during reprocessing.	17/10/2016	-	Update of https://pro.soluscope.com
06/07/2016	Connector for Olympus scope	WO-AW	The WO-AW has been upgraded with new metal ring to improve grip when inserted in the endoscope	06/07/2016	-	Update of https://pro.soluscope.com
06/07/2016	Connector for GE Storz endoscope	WS-AW	The WS-AW replaces the WO-AW for Air/water connection to GE Silver line Storz scope.	06/07/2016	-	Update of https://pro.soluscope.com
13/05/2016	Connector for FujiFilm EG-580UT/UR endoscope	WF-B580U WF-BAL-UR WF-BAL-UT	New connectors for Fujifilm UltraSound scopes	13/05/2016	-	Update of https://pro.soluscope.com
13/05/2016	Air connetcor for Fujifilm GI Scope	WF-AW WF-AW-530S2	The air connector features an additional inox plate to protect the connector from endoscope air pipe during the insertion.	13/05/2016	-	Update of https://pro.soluscope.com
14/04/2016	Silicone based lubricant Tools kit for seals	B8000 KIT-MAJ joints	Use of lubricant is recommended for connectors' seals maintenance. The tools set allows quick replacement of all seal types.	14/04/2016	Informdis 3-2016	
31/03/2016	Suction connector for FujiFilm bronchoscope	SL-S1-F-530 SL-S1-F-530US	The suction connector is changed with right-angle connector. It facilitates the insertion and placement in Serie ENT bowl.	31/03/2016	-	-
23/09/2015	Air/Water connector for Olympus 140 to 190 Serie	WO-AW190N	This reference is discontinued. It is replaced with the WO-AW190S connector.	23/09/2015	Informdis 2-2015	-
08/07/2015	Biopsy/Suction connector for Fujifilm G5 endoscopes	WF-BAS	New reference for Fujifilm G5 endoscopes with improved suction stainless steel connector.	08/07/2015	Informdis 1-2015	Update of www.mysoluscope.com
08/07/2015	Air/Water connector for Olympus 140 to 180 Serie	WO-AW140N	This reference is discontinued. It is replaced with the WO-AW190N connector.	08/07/2015	Informdis 1-2015	Update of www.mysoluscope.com
27/05/2015	Air/Water connector for Endochoice Fuse™ Endoscope	WE-AW	New reference for Fuse 1C and 1G Endoscope Air/Water connector.	27/05/2015	-	Refer to Communication Endochoice Fuse 040115 document
30/04/2015	Leak test connector for FujiFilm endoscope	SL-TO-F	New semi-transparent tube is introduced. It allows user checking visually that no water or humidity is in the tube due to inadequate connector storage and prevents any risk to introduce water or humidity in the endoscope through the leak test connector.	30/04/2015	-	-
24/04/2015	Biopsy/Suction connector for Storz video bronchoscope	WS-BAX	New reference for 11301 BNX endoscope.	24/04/2015	-	Update of www.mysoluscope.com
01/04/2015	Leak test connector for Machida flexible endoscope	SL-TO-M	New reference for leak test of Machida flexible endoscope product range. Applicable for all Soluscope AERs.	01/04/2015	-	-
25/02/2015	Channel selector obturator for Ultra Sound Pentax endoscope	SL-BLOCK-PENT	This reference replaces SL-BLOCK-135 connector. SL-BLOCK-PENT offers higher grip for improved connection reliability. SL-BLOCK-135 is discontinued.	25/02/2015	-	Update of www.mysoluscope.com (S3P-D, S3P-K and S3P-L connector set)

05/02/2015	Biopsy/Suction connector for Olympus Bronchoscope	WO-BAB-40S	This reference replaces WO-BAB-40 connector. WO-BAB-40S features new biopsy stainless connector for improved connection reliability. WO-BAB-40 is discontinued.	05/02/2015	-	Update of www.mysoluscope.com (S30-J and S30-K connector set)
09/01/2015	Blocker for Fujifilm and Olympus endoscope	SL-BLOCK-140	Change has been applied on the product to feature a new inox insertion base and improve mechanical reliability. Previous version is discontinued, new part can be ordered with the same Reference code.	09/01/2015	-	Applies from batch 11647. Update of www.mysoluscope.com (S3F-G connector set)
02/10/2014	Air/Water connector for Fujifilm endoscope	(1875)	Change of Air/Water connector to improve the sealing reliability when submitted to lateral mechanical effort. WF-AW and WF-AW-530S2 are impacted and updated with the new connector. Will be applied when previous version stock is depleted.	02/10/2014	-	Update of www.mysoluscope.com
29/07/2014	Leak test connector for GF-UCT180 Olympus endoscope	SL-TO-O-UL	Dual leak test connector for specific GF-UCT180 endoscope	29/07/2014	-	Update of www.mysoluscope.com
29/07/2014	Blocker for Olympus echo-endoscope, serie 140-160-180	SL-BLOCK2	New blocker to facilitate the connection to Olympus echo-endoscope specific shape cylinders. SL-BLOCK1 is still available for other endoscopes/configurations	29/07/2014	-	Update of www.mysoluscope.com
16/05/2014	Biopsy/Suction connector for Fujifilm and Olympus	WO-BA	O'ring seal and internal connector profile have been improved for better durability. There is no impact on usability.	01/06/2014	-	-
06/05/2014	Air/Water connector for Olympus 190 Serie	WO-AW190	End-Of-Life. Replaced with WO-AW190N	06/05/2014	Informdis 6-2014	Update of www.mysoluscope.com
06/01/2014	Blocker for Pentax Endoscope	WP-B	Due to obsolescence, change of the metal sleeve of the part. No impact on use.	06/01/2014	-	-
20/12/2013	Olympus Serie 185	-	Qualification of Olympus Serie 185 endoscopes for Serie 4 and Soluscope 3 AERs.	20/12/2013	-	Update of www.mysoluscope.com
07/10/2013	Fujifilm Serie 600	-	Qualification of Fujifilm Serie 600 endoscopes for Serie 4 and Soluscope 3 AERs.	07/10/2013	-	Update of www.mysoluscope.com
07/10/2013	Fujifilm EN-580T	-	Qualification of Fujifilm EN-580T endoscope for Serie 4 and Soluscope 3 AERs.	07/10/2013	-	Update of www.mysoluscope.com
17/09/2013	Blocker for Endochoice endoscope	WE-B	Launch of the WE-B Blocker for compliance with Endochoice Fuse 1 Endoscope	17/09/2013	-	Read "Communication Endochoice Fuse - 091213" document for more information
16/09/2013	Air-Water Connector for Olympus endoscope	WO-AW190	Launch of the WO-AW190 for compliance with Olympus Exera III serie (190)	20/09/2013	-	Update of www.mysoluscope.com
09/07/2013	Air Connector for Fuji	(3077)	Change of Air connector design for Fuji endoscope. Improve reliability and connexion to the endoscope	09/07/2013	-	Applied to WF-AW and WF-AW-530S2 references. Update of drawing in mysoluscope.com

* : () indicates Soluscope internal reference; part is not available for selling