






PORTHOS INSTRUMENTS LIST (PORTHOS-1010)

NUMBER	INSTRUMENT	REFERENCE NUMBER	SERIAL NUMBER	LOT NUMBER	IMAGE	UNIT	SET NUMBER TO BE PRODUCED
1	AWL	PRT-AW-1001				1	
2	PEDICLE PROBE STRAIGHT	PRT-PPS-1002				1	
3	PEDICLE PROBE CURVED	PRT-PPC-1003				1	
4	PROBE FEELER STRAIGHT	PRT-PFS-1004				1	
5	PROBE FEELER CURVED	PRT-PFC-1005				1	
6	MARKER-RIGHT	PRT-MR-1014				4	
7	MARKER-LEFT	PRT-ML-1015				4	
8	ROD WRENCH	PRT-RW-1016				1	
9	T HANDLE A0	PRT-OSD-1006				1	
10	DEPTH GAUGE	333-DG				1	
11	DRILL-Ø3.5-Ø4.0(A0)	PRT-DR35-1007				1	
12	TAP -Ø3.5-Ø4.0(A0)	PRT-TP35-1008				1	
13	PORTHOS DRILL GUIDE	PRT-TP35-1009				1	
14	POLYAXIAL SCREW DRIVER	PRT-PSD-1011				2	
15	POLYAXIAL SCREW SHAFT DRIVER	PRT-PCHD-1034				1	
16	ALIGNMENT TOOL	PRT-ALT-1012				1	
17	PERSUADER	PRT-PSU-1013				1	
18	STRAIGHT HANDLE-(A0)	H170-A0				2	
19	TORQUE HANDLE-(5NM)	STNDRT-5NM				1	
20	ANTI-TORQUE	PRT-AT-1035				1	
21	TRANSVERSE CONNECTOR DRIVER	333-MTCD				1	
22	NUT STARTER-(T20)	PRT-NS-T20				2	
23	NUT(T20) DRIVER SHAFT-(T20)	PRT-NDS-T20				2	
24	OCCIPITAL SCREW STARTER	PRT-OSS-AA3				1	
25	OCCIPITAL SCREW-DOMINO DRIVER SHAFT	PRT-SSD-1018				1	
26	HOOK INSERTER	PRT-HI-1030				1	
27	HOOK PUSHER	PRT-HP-1031				1	
28	HOOK ELEVATOR LAMINA	PRT-HEL-1033				1	

29	PORTHOS ROCKER	PRT-RCR-1034				1	
30	ROD HOLDER STRAIGHT	PRT-RHS-1019				1	
31	ROD HOLDER CURVED	PRT-RHC-1020				1	
32	TRANSVERSE CONNECTOR HOLDER	PRT-TCH-1028				1	
33	OCCIPITAL PLATE HOLDER	PRT-OPH-1039				1	
34	TRIAL ROD (200mm)	PRT-TR-1020				1	
35	INSTUTU BENDER RIGHT	PRT-IBR-1038				1	
36	INSTUTU BENDER LEFT	PRT-IBL-1038				1	
37	OCCIPITAL PLATE BENDER	PRT-OPB-1040				2	
38	DISTRACITOR	PRT-DST-1021				1	
39	COMPRESSOR	PRT-CMP-1022				1	
40	ROD BENDER	PRT-RB-1023				1	
41	ROD CUTTER	PRT-RC-1024				1	
42	OCCIPITAL PLATE TRANS. CONN. CADDIES	PRT-OPC-1041				1	
43	OCCIPITAL SCREW CADDIES (Ø4-Ø4.5)	PRT-OSC-1042				1	
44	PORTHOS CONNECTOR CADDIES	PRT-LDLC-1043				1	
45	NUT CADDIES	PRT-NC-1044				1	

46	POLYAXIAL SCREW CADDIES (Ø3.5)	PRT-PSC35-1045				1	
47	POLYAXIAL SCREW CADDIES (Ø4)	PRT-PSC40-1046				1	
48	LID (GREEN)	111-LID				2	
49	CONTAINER 01 (OUTSIDE:600x272x190mm) (INSIDE:543x258x184mm)	PRT-COA-01				1	
50	CASE 01-01 (540x250x50mm)	PRT-COA-0101				1	
51	CASE 01-02 (540x250x50mm)	PRT-COA-0102				1	
52	CASE 01-03 (540x250x50mm)	PRT-COA-0103				1	
53	CONTAINER 02 (OUTSIDE:600x272x190mm) (INSIDE:543x258x184mm)	PRT-COB-02				1	
54	CASE 02-01 (540x250x50mm)	PRT-COB-0201				1	
55	CASE 02-02 (540x250x50mm)	PRT-COB-0202				1	
56	CASE 02-03 (540x250x50mm)	PRT-COB-0203				1	
57	SILICONE GRASS	PRT-SLC-01				1	
58	ROD CUTTER(LARGE MODEL) (EXTRA)	PRT-RC-1025				1	

PORTHOS SET 1 - ISOMETRIC VIEW




PORTHOS SET 1 - TOP VIEW



PORTHOS SET 1 - CLOSED VIEW



PORTHOS SET 2 - ISOMETRIC VIEW



PORTHOS SET 2 - TOP VIEW



PORTHOS SET 2 - CLOSED VIEW

