## LOG OF APPROVED SUPPLEMENTS

SUPP.

SUPPLEMENT NAME

REVISION LEVEL EQUIPMENT INSTALLED

Vaccine Scattering

SUPPLEMENT No.

Cessna 172RG

Vaccine Scattering

Registration No. Serial No.

172RG-0908 OK - ELS

Revision No. NZ AE/128-DLP1 to AFM Supplement 172RG, is approved under the autority of DOA ref. EASA.21J.094

Approved (CVE): Ing. Miroslav Mikel

Date: 07. 03. 2014

1/2

NZ AE/128-DLP1

Sept 12/12

This supplement supplies the information necessary for the efficient operation of the airplane when the Vaccine Scattering is installed. The information contained within this supplement is to be used in conjunction with the complete AFM.

This supplement is a permanent part of this AFM and Wratimovská 69/335

Tis 00 Ostrava - Kunčičky DIČ: CZ47155086 EASA.21J.094 Scattering is installed must remain in this AFM at all times when the Vaccine

Revision No. NZ AE/128-DLP1 to AFM Kevision No. NZ AE/128-DLP1 to AFM Supplement 172RG, is approved under the autority of DOA ref.

Date: 07. 03. 2014

Approved (CVE): Ing. Miroslav Mikel Mr fr

CONFORM CU

**ØRIGINALUL** 

Sept 12/12

NZ AE/128-DLP1

1/4

2/4

NZ AE/128-DLP1

Sept 12/12

Intentionally left blank

Vaccine Scattering

LOG OF REVISION

CESSNA MODEL 172RG

PILOT'S OPERATING HANDBOOK SUPPLEMENT

			No.
*			Pages
			Description of Revision
			CAA Approved
	/2		Date

Vratimovská 69/335
718 00 Ostrava - Kunčičko DIČ: CZ47155086

CONFORM CU ORIGINALUL

## SECTION 2

If the the dropping equipment is installed, the aeroplane must be operated in the NORMAL CATEGORY only. The speed is to be kept between 80 -105 KIAS during the vaccine

application process.

operator is on board of the plane as well. It is required that except for the pilot the dropping equipment

**EMERGENCY PROCEDURES - Not Affected** SECTION 3

NORMAL PROCEDURES - Not Affected SECTION 4

PERFORMANCE - Not Affected **SECTION 5** 

WEIGHT & BALANCE/EQUIPMENT LIST - Not Affected SECTION 6

**AIRPLANE & SYSTEMS DESCRIPTIONS** SECTION 7

The dropping equipment for rabies vaccine scattering is installed. The dropping equipment operator sits on the right seat rotated be fastened. backwards during takeoff and landing. The operator's seat belts shall

CONFORM CU ORIGINALUL

Vratimovská 69/335
718 00 Ostrava - Kunčičky
DIČ: CZ47155086

NZ AE/128-DLP1

Sept 12/12

3/4

Vaccine Scattering

PILOT'S OPERATING HANDBOOK SUPPLEMENT

The engine power setting – as required to keep the horizontal flight. The dropping equipment operator does not have to be fastened by seat belts during the dropping equipment operation.

SECTION 8
AIRPLANE HANDLING, SERVICE & MAINTENANCE
- Not Affected

SECTION 9
SUPPLEMENTS

Issued Vaccine Scattering supplement.

CONFORM CU ORIGINALUL

Vratimovská 69/335 718 00 Ostrava - Kunčick DIČ: CZ47155086