



Thunder Sky Winston

产品合格证

QUALITY CERTIFICATE

型号规格
SPECIFICATION

TSWB-LYP160AHA

出厂编号
PRODUCT NUMBER

00001


检验员
CHECKER



检测日期
CHECK DATE

20250805

结论：检验结果符合该产品技术要求
CONCLUSION: The product is qualified to its standard.



雷天温斯顿电池
THUNDER SKY WINSTON BATTERY



注意事項 CAUTIONS

■本产品电池出厂时，不得直接进行放电。
首次使用务必：

- 1、将单体电池进行恒电流0.3CA-0.5CA充电至限制电压3.8V后停止充电。
- 2、如电池组首次使用必须依据我司电池《使用说明书》标准充放电(表三)进行充满电后方可使用放电。
- 3、电池串联使用必须采用符合本产品充电设备及BMS结合才能使用。

■电池在运输过程中，不得受剧烈机械冲撞、爆晒、雨淋。

■电池在装卸过程中，应轻搬轻放，严禁摔掷、翻滚、重压。

■不能重压，不能重叠放置。

■产品贮存在温度为 $25^{\circ}\text{C} \pm 5^{\circ}\text{C}$ 的干燥、清洁、通风的仓库内。

■不受阳光直射，远离热源不少于2米。

■严禁短路。

■When shipped from the factory, this cell CANNOT be discharged directly under any condition.

Before the first use :

1. The single cell must be charged at constant current of 0.3CA-0.5CA and the cell should not be charged till the charging voltage reaches 3.8V .
2. The battery pack must be fully charged under the instruction of Operator's Manual -- Battery Pack's Standard Charge and Discharge Current and Voltage (Chart 3) .
3. If the batteries are used in series, they must be adopted with the proper charging equipment and BMS accordingly.

■Avoid shock, sunshine and rainwater in the shipment

■Do not knock, welter or stress during loading and unloading

■Do not lap over.

■The battery should be stored in clean, dry and ventilated warehouse at temperature of $25^{\circ}\text{C} \pm 5^{\circ}\text{C}$

■Be away from direct sunlight and away from heat no less than 2 meters.

■Short circuit is not allowed.

国际销售
International Sales

雷天温斯顿电池股份有限公司
THUNDER SKY WINSTON BATTERY INCORPORATION COMPANY LIMITED

中国生产基地
Production Base in China

东方醒狮储能电池有限公司
ORIENTAL SMART LION ENERGY STORAGE BATTERY LIMITED

TEL: 86-0596-818 6789
Fax: 86-0596-818 6678

<http://www.thundersky-winston.com>
E-mail: winston@thundersky-winston.com

中国福建省漳州市长泰经济开发区
CHANGTAI INDUSTRIAL ZONE, ZHANGZHOU CITY,
FUJIAN PROVINCE, CHINA.