

Sizes and Conversion Table

Colour Code

Ø mm	1 ² / ₃	2	2 ² / ₃	3 ¹ / ₃	4	4 ² / ₃	5 ¹ / ₃	6
CH / FG	5	6	8	10	12	14	16	18

Ø mm	6 ² / ₃	7 ¹ / ₃	8	8 ¹ / ₃	8 ² / ₃	9 ¹ / ₃	10	10 ² / ₃
CH / FG	20	22	24	25	26	28	30	32

Charrière =
mm x 3

French =
identical with charrière

Gauge =
US.measurement

Charrière / F in mm	
1 ¹ / ₃ mm = 1 CH / F	8 mm = 24 CH / F
2 ² / ₃ mm = 2 CH / F	8 ¹ / ₃ mm = 25 CH / F
1 mm = 3 CH / F	8 ² / ₃ mm = 26 CH / F
1 ¹ / ₃ mm = 4 CH / F	9 mm = 27 CH / F
1 ² / ₃ mm = 5 CH / F	9 ¹ / ₃ mm = 28 CH / F
2 mm = 6 CH / F	9 ² / ₃ mm = 29 CH / F
2 ¹ / ₃ mm = 7 CH / F	10 mm = 30 CH / F
2 ² / ₃ mm = 8 CH / F	10 ¹ / ₃ mm = 31 CH / F
3 mm = 9 CH / F	10 ² / ₃ mm = 32 CH / F
3 ¹ / ₃ mm = 10 CH / F	11 mm = 33 CH / F
3 ² / ₃ mm = 11 CH / F	11 ¹ / ₃ mm = 34 CH / F
4 mm = 12 CH / F	11 ² / ₃ mm = 35 CH / F
4 ¹ / ₃ mm = 13 CH / F	12 mm = 36 CH / F
4 ² / ₃ mm = 14 CH / F	12 ¹ / ₃ mm = 37 CH / F
5 mm = 15 CH / F	12 ² / ₃ mm = 38 CH / F
5 ¹ / ₃ mm = 16 CH / F	13 mm = 39 CH / F
5 ² / ₃ mm = 17 CH / F	13 ¹ / ₃ mm = 40 CH / F
6 mm = 18 CH / F	13 ² / ₃ mm = 41 CH / F
6 ¹ / ₃ mm = 19 CH / F	14 mm = 42 CH / F
6 ² / ₃ mm = 20 CH / F	14 ¹ / ₃ mm = 43 CH / F
7 mm = 21 CH / F	14 ² / ₃ mm = 44 CH / F
7 ¹ / ₃ mm = 22 CH / F	15 mm = 45 CH / F
7 ² / ₃ mm = 23 CH / F	15 ¹ / ₃ mm = 46 CH / F

Gauge in mm
11 G = 2.95 mm
12 G = 2.64 mm
13 G = 2.34 mm
14 G = 2.03 mm
15 G = 1.83 mm
16 G = 1.63 mm
17 G = 1.44 mm
18 G = 1.22 mm
19 G = 1.02 mm
20 G = 0.91 mm
21 G = 0.81 mm
22 G = 0.71 mm
23 G = 0.61 mm
24 G = 0.56 mm
25 G = 0.51 mm
26 G = 0.46 mm
27 G = 0.42 mm
11 G = 2.95 mm
11 G = 2.95 mm
11 G = 2.95 mm