

Gantry, front - service parts					10188608	
ID	Part-No.	Description	NSI	TC	Wgt.	Type
		Comment When replacing DMS M6 (10023450) by DMS B-LC (7273530) additionally the conversion kit (10186142) must be ordered. Info for MI: for systems with VG60 or higher			KG	
>	DMS F-ST	(10186150) DMS P46F-ST (128 slice configuration) Stellar Detector optional for AS+ (128 slice configuration).			170,000	
+	2 REP	10141785 STRATON MX P Order additionally Biograph Lifting Kit Tool Part No. 10244855.		1	106,000	
+	3 REP	10141790 Cooling unit P46		1	82,000	
+	4 REP	10663083 XGR-Box 2 Service Part For Systems with SW equal and higher VA48-SP8A or VB10A-SP04 (minimum requirement for VB10A) or VB20A-SP06 (minimum requirement for VB20A) or VB30A Service kit contain XGR-Box P/N 10663081. For MI! Now supported for MI systems running VG62D, VG70E, VG76C, and VG80C.		1	27,000	
+	REP	08365988 Service Part Matrix XGR-Box This part is reserved for CT systems with VA40/VA60 and VA10 before SP06, VA44		1	27,000	