

ZERTIFIKAT | CERTIFICATE | CERTIFICAT | CERTIFICADO | СЕРТИФИКАТ | شهادة | 证书 | 인증서



CERTIFICATE OF CONFORMITY

Certificate - No.: 18-IS-2041-TAT-20-MAD-2276

Applicant : MST CONSTRUCTION EQUIPMENT YATIRIM A.Ş.
4. Organize Sanayi Bölgesi 83426 Nolu Cadde No:1, Şehitkamil
Gaziantep / Turkey

Manufacturer : MST CONSTRUCTION EQUIPMENT YATIRIM A.Ş.
4. Organize Sanayi Bölgesi 83426 Nolu Cadde No:1, Şehitkamil
Gaziantep / Turkey

Equipment : Backhoe Loader

Type/Model(s) : # M642, M642 PLUS, M644, M644 PLUS #

Standard(s) / Certification Basis : 2006/42/EC Machinery Directive
2014/30/EU Electromagnetic Compatibility Directive
2000/14/EC Noise Emission by Outdoor Equipment Directive
EN ISO 12100:2010,
EN 474-1:2006+A4:2013/AC:2014,
EN 474-4:2006+A2:2012,
ISO 13766-1:2018, ISO 13766-2:2018,
ISO 6393:2008, ISO 6394:2008, ISO 6395:2008, ISO 6396:2008,

This Certificate of Conformity is issued on a voluntary basis according to Machinery Directive 2006/42/EC. It conforms that the listed equipment complies with the essential safety requirements of the directive. It refers only to the sample and its technical file submitted for conformity assessment.

Inspection Report No : 18-IS-2041-UDR-06

Issue Date : 07.12.2020

Expiry Date : 06.12.2021

The certificate is valid as long as the standards and legislation are current and annual audit is performed with satisfactory results.

For and on behalf of
TÜV AUSTRIA TURK Belgelendirme
Eğitim ve Gözetim Hizmetleri Ltd. Şti.
Ali Osman ÖZVEREN



After preparation of the necessary technical documentation as well as the declaration of conformity the required CE marking can be affixed on the product. Other relevant directives have to be observed.

This Certificate of Conformity has been granted to the applicant based on the results of testing performed by the applicant/manufacture or an accepted laboratory and the consequent review of the test report by TÜV Austria Turk. Revisions to the referenced certification basis or any change of the design, materials, components or processing may require the repetition of all or some of the qualification tests in order for the test report and therefore this associated certificate to remain valid.