


M102 assembly in Contr.cabinet Artis dXX

Title	Page	Refer...
Artis zee	1	0304...
Artis zee biplane	2	1009...
STD floor	3	1039...
Second plane FD	12	0664...
STD ceiling Card	21	1039...
STD ceiling Angio	24	1039...
Floor Mout.Table (Basic)	25	0576...
Floor Mout.Table (Stepping)	34	0576...
Floor Mout.Table (Stepp./Tilt)	39	0576...
OP Table	45	0576...
FD 20x20 / 4800	51	0755...
FD 30x40 / 3040CV	52	1050...
FD 30x40 / 4700	53	0755...
FD 20x20 new IF RoHs / 4800	54	1050...
FD 30x40 new IF RoHs / 4700	55	1050...
Detector Cooling Unit	56	0755...
FD Cooling unit SMC	57	1050...
FD cooling unit Compact SMC	58	1084...
AXIS Biplane BB	59	1041...
AXIS Biplane BB1	77	1060...
AXIS Biplane VD	80	1076...
FD RTC V5	93	1050...
FD RTC V5 (RoHS)	94	1050...
FD RTC V5 Mk.II	95	1150...



M102 assembly in Contr.cabinet Artis dXX 01298533

ID	Part-No.	Description	NSI	TC	Wgt.	Type
		Comment			KG	
+	1 03085305	AC-DC 230VAC 24V/3.8A 91W =D= (not for AXIOM Artis systems dFCM +dBCM)		1	5,020	B3305
+	11115695	FD accessory set FD/detector power supply		1	0,990	
+	2 03086956	Timing Relay 24/230V 5s-100s =D= K3		2	0,310	B0401
+	3 10359171	D102 External Interface/Reset Board Only for Artis zee from VC14		1	0,370	
+	05549279	Reset Board Kit		1	0,370	