









7



Układ krzywek
SK10;16;20G/7.12127

7

SK10;16;20G/7.12127

A circular arrangement of numbers 1 through 12. The number 1 is at the top, 7 is at the bottom, and the others are arranged clockwise in between.

5	2	N20	KRZYWKA SK10-6610-N
4	2	N16	KRZYWKA SK10-6610-N
3	2	N05	KRZYWKA SK10-6610-N
2	2	N02	KRZYWKA SK10-6610-N
1	6	N01	KRZYWKA SK10-6610-N
	1	RD3	NAPĘD SK10-1402
PNZ	SZT	WYK	NAZWA

Program łączeń