

Specificația pentru lucrări de deservire echipamente de răcire și ventilare

Lista de prețuri

Nr.	Denumire sistem climatizare	Cantitate bucati	Periodicitate deservire anuală, set	Preț unitar, lei	Suma lei, fără TVA
1	Condiționar DAIKIN tip VRV	61	2	550.00	68200.00
2	Sistem de refulare	2	2	1500.00	6000.00
	Total anual, fără TVA				74200.00

Lista Echipamentelor de răcire și ventilare cu locul amplasării

Nr.	Denumirea echipamentului de răcire și ventilare	Locul amplasări
1	Bloc interior "Daikin" FBQ 60C8	et. 7
2	Bloc interior "Daikin" FBQ 100C8	et.7
3	Bloc interior "Daikin" FXDQ15P7	et.6
4	Bloc interior "Daikin" FXDQ25P7	et.6
5	Bloc interior "Daikin" FXDQ63P7	et.6
6	Bloc interior "Daikin" FXDQ40P7	et.6
7	Bloc interior "Daikin" FXDQ40P7	et.6
8	Bloc interior "Daikin" FXDQ40P7	et.6
9	Bloc interior "Daikin" FXDQ25P7	et.6
10	Bloc interior "Daikin" FXDQ25P7	et.6
11	Bloc interior "Daikin" FXDQ15P7	et.6
12	Bloc interior "Daikin" FXDQ15P7	et.6
13	Bloc interior "Daikin" FXDQ15P7	et.6
14	Bloc interior "Daikin" FXDQ25P7	et.6
15	Bloc interior "Daikin" FXDQ40P7	et.6
16	Bloc interior "Daikin" FBQ 71C8	et.7
17	Bloc interior "Daikin" FBQ 60C	et.7
18	Bloc interior "Daikin" FXDQ40P7	et.6
19	Bloc interior "Daikin" FXDQ15P7	et.6
20	Bloc interior "Daikin" FXDQ15P7	et.6
21	Bloc interior "Daikin" FXDQ15P7	et.6
22	Bloc interior "Daikin" FXDQ15P7	et.6
23	Bloc interior "Daikin" FXDQ25P7	et.6
24	Bloc interior "Daikin" FXDQ32PA	et.6
25	Bloc interior "Daikin" FXDQ32PA	et.6
26	Bloc interior "Daikin" FXDQ32PA	et.6
27	Bloc interior "Daikin" FXDQ32PA	et.6
28	Bloc interior "Daikin" FXDQ32PA	et.6
29	Bloc interior "Daikin" FXDQ32PA	et.6
30	Bloc interior "Daikin" FXDQ15P7	et.6
31	Bloc interior "Daikin" FXDQ32PA	et.6
32	Bloc interior "Daikin" FXDQ25P7	et.6

33	Bloc interior "Daikin" FXDQ25P7	et.6
34	Bloc interior "Daikin" FXDQ32PA	et.6
35	Bloc interior "Daikin" FXDQ25P7	et.6
36	Bloc interior "Daikin" FXDQ15P7	et.6
37	Bloc interior "Daikin" FXDQ25P7	et.6
38	Bloc interior "Daikin" FXDQ25P7	et.6
39	Bloc interior "Daikin" FXDQ15P7	et.6
40	Bloc interior "Daikin" FXDQ15P7	et.7
41	Bloc interior "Daikin" FDXS25F	et.5
42	Bloc interior "Daikin" FDXS25F	et.5
43	Bloc interior "Daikin" FDXS35F	et.5
44	Bloc interior "Daikin" FDXS35F	et.5
45	Bloc interior "Daikin" FDXS35F	et.5
46	Bloc interior "Daikin" FDXS50F9	et.5
47	Bloc interior "Daikin" FDXS50F9	et.5
48	Bloc interior "Daikin" FDXS50F9	et.5
49	Bloc interior "Daikin" FDXS60F	et.5
50	Bloc interior "Daikin" FDXS25F	et.6
51	Bloc interior "Daikin"	centrul comercial
52	Bloc interior "Daikin"	centrul comercial
53	Bloc interior "Daikin"	centrul comercial
54	Bloc interior "Daikin"	centrul comercial
55	Bloc interior Ballu	Vadul lui vodă
56	Bloc interior Ballu	Vadul lui vodă
57	Bloc interior Ballu	Vadul lui vodă
58	Bloc interior Ballu	Vadul lui vodă
59	Bloc interior Ballu	Vadul lui vodă
60	Bloc interior Ballu	Vadul lui vodă
61	Bloc interior Ballu	Vadul lui vodă