



Nº original	Semnatura si data	Nº modificat


GTS Nr.1 Etajul 2
Sc.1:100




GTS Nr.2 Etajul 2
Sc.1:100




GTS Nr.3 Etajul 1
Sc.1:100




GTS Nr.4 Etajul 2
Sc.1:100




GTS Nr.5 Etajul 2
Sc.1:100




GTS Nr.6 Etajul 1
Sc.1:100



GTS Nr.7 Etajul 2
Sc.1:100



-  -Vas closet dimensiunile si culoarea a se coordona cu beneficiarul
-  -Lavaor dimensiunile si culoarea a se coordona cu beneficiarul

						Dets Sectorul Buiucani			
						Scoala Primara nr. 91 „A. Ursu”			
Sch.	Cant.	Foaia	N.doc.	Semn.	Data	Reparatie GTS	Etapa	Plansa	Planse
Elaborat		Jornea Lilia			"		PE	1	PE
Verificat		DETS Buiucani			"				