



广微测  
Gmicro Testing

GUANGDONG DETECTION CENTER OF MICROBIOLOGY

REPORT FOR ANALYSIS

Report No.

2018FM01526R01E

Name of Sample

Airdog X5 Air Purifier

Applicant

Suzhou BeiAng Air Tech Ltd.

Test Type

Entrustment Test



Address: Building 59, No.100 Central Xian Lie Road, Guangzhou, China

Postcode: 510070

Tel: +86 20 87137666

Fax : +86 20 87137668

Website : [www.gddcm.com](http://www.gddcm.com)





**广微测**  
Gmicro Testing

**GUANGDONG DETECTION CENTER OF MICROBIOLOGY**



**REPORT FOR ANALYSIS**

Report No.:2018FM01526R01E Verification Code: 32716408

Name of Sample	Airdog X5 Air Purifier	Test Type	Entrustment Test
Applicant	Suzhou BeiAng Air Tech Ltd.	Address	No.188 xincheng Road.,SIP, Suzhou,Jiangsu, China,
Sample Source	Submitted for Testing by the Applicant	Sample Quantity	One Sample Submitted
Spec and Lot No of Sample	KJ300F-X5 Master-test, Cover type KJ300F-X3	State and Characteristic	Household appliances
Sample Received Date	2018-03-05	Test Completion Date	2018-03-26
Test Standard and Method	Refer to Technical Standard for Disinfection (2002 Ministry of Health P.R.China)-2.1.3		
Item Tested	Identification test of aerosolized virus elimination effect		
Test Conclusion	The test data of the sample(s) is attached to the page(s) of this report.		
Remarks	<p>1. Manufacturer: AnHui BeiAng Air Tech Ltd. (provided by the applicant)</p> <p>2. The sample KJ300F-X5 is add WIFI module to KJ300F-X5, no other difference. (provided by the applicant)</p>		

生物  
检测

Issue Date: 2018-04-09



Editor: *Chen Yingting*

Verifier: *Sun Jias*

Approver: *Xie Xiaobao*





ANALYSIS AND TEST RESULT

Report No.: 2018FM01526R01E

Action Time	Virus and host cell	Data point	Aerosolized virus concentration in the test chamber (IU/m <sup>3</sup> )	Removal rate (%)
1h	H3N2 Influenza virus Host cell: MDCK	Before test	1.4×10 <sup>6</sup>	/
		After test	6.1×10 <sup>2</sup>	

Note: The natural decay of the microorganisms in the air has been eliminated.  
(blank below)

分析  
专用

Remarks	1.The experiment was performed in a 10m <sup>3</sup> test chamber 2. Working state: Press L4( the speed ) to test.
---------	---



Report No.: 2018FM01526R01E

## Notice Items

1. The Test report is invalid if not affixed with Authorized Stamp of Test and Paging Seal.
2. The Test report is invalid without signature of verifier and approver.
3. The Test report is invalid if being supplemented, deleted or altered.
4. Without prior written permission, the report cannot be reproduced, except in full.
5. Unless otherwise stated, the results shown in this test report refer only to the sample(s) submitted.
6. Any dispute of the report must be raised to the testing body within 15 days after the report is received, exceeding which the dispute will not be accepted.
7. For the tested sample(s) submitted by the applicant, the sample information in the test report is provided by the applicant and the laboratory is not responsible for its authenticity.
8. This test report is for reference only to the applicant and does not have a proof of effect for others.

检测中心章