

Graficul de executare a lucrărilor

Reparatia Gradinitei de copii din satul Puhoi r-I Ialoveni

	2018															2019														
Denumirea lucrarilor																														
																	+	+	+	+	+	+	+	+	+					
Tavan																														
Pereti	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+													
Pardosele	+																+	+	+	+	+	+	+	+	+	+	+	+		
Incalzirea1+2ciclu	+													+	+													+	+	
Electricitate1+2ciclu	+	+	+	+																									+	
Intrarea in gradinita																												+	+	

Director

Cebotarenco Mihail

