

REQUESTED BY	CUSTOMER	WORK NUMBER	SITE NAME
EPM Romania	BIOMARKET	361108	CEADIR-LUNGA
EQUIPMENT	SERIAL NUMBER	ODORIZER TYPE	DATE
DO/200	DR408/24	TBM	1/10/2024

Pneumatic Pannel tag DR339/23.

All tubing and connections between Do/200 panel and tank made in according with the instruction manual.

Electronic Control Unit

All wire connections were checked with positive results.

A D1030D BARRIER for digital flow input was installed inside ECU.

The connections between flow computer and D1030D inside Do/200 was made by me and tested with positive results

DO/200 Configuration.

- Cylinder on (min 100mm/ max 500mm)
- Absorption on
- Injectors L-H
- Fail nc
- Analog output c
- User: MTG Pa
- Ip plc 255.0
- Ip hmi 255.0
- Gateway 255.0
- Language Romanian.



Field Test

No leaks were detected on the system.

The two injectors L-H off were tested with positive results.

All system alarms have been tested with positive results.

Successful testing under the supervision of the customer Moldova Trans Gaz.

Conclusions.

- The Do/200 system work properly.
- The system was left in automatic mode.

CEADIR-LUNGA 1/10/2024

