



# TEST REPORT

NO.: ECT2019K040218-Y1

Date: Apr. 10, 2019

Page 1 of 4

**Applicant:** SC “LED MARKET” SRL

**Address:** Republica Moldova  
mun.Chisinau, sos. Muncesti 801, MD-2029

Cod fiscal: 1004600060124

**Tel:** +373 (22) 496 584

**Email:** trade@compuvad.com

**URL:**www.ledmarket.md

**Report on the submitted sample said to be:**

**Sample name:** LED street light

**Model:** Range Leaf,sizes G1200, G1700, G2600, G3500, G3800, G5200

**Trademark:** Leaf Range

**Manufacturer:** SC “LED MARKET” SRL

**Sample received date:** Apr. 02, 2019

**Testing period:** From Apr. 02, 2019 to Apr. 10, 2019

**Testing Requested:**

According to customer requirements, to do IK08 test on the submitted sample(s).

**Test Method:**

According to the condition submitted by the client.

Signed for and on behalf of  
Shenzhen ECT Testing Technology Co., Ltd

Prepared by: Eris  
Zeng Ji Lan, Eris  
Report Clerk

Reviewed by: Lewis  
Liu Lin Wen, Lewis  
Laboratory Supervisor

Approved by: Jeewah  
Lv Jie Hua, Jeewah  
Technical Director





# TEST REPORT

NO.: ECT2019K040218-Y1

Date: Apr. 10, 2019

Page 2 of 4

## Test Condition:

- 1) Ambient temperature and relative humidity: 23.5°C, 58% RH
- 2) Test condition:
  - a) The sample is placed on the ground, The energy of impact test specimens for 1J;
  - b) The impact point is uniformly distributed on the sample
  - c) Check the samples after test

## Test Equipment:

Equipment	Manufacturer	Model	Calibration Date
IK Impact Tester	Hanyang	HY-7812A	2019-03-15

# TEST REPORT

NO.: ECT2019K040218-Y1

Date: Apr. 10, 2019

Page 3 of 4

## Test Result:

Test Item	Criteria (According to the technical requirements of client)	Test Result	
IK08	No crack on the sample	After the test, there is no obvious appearance abnormality on the sample.	P

## Photos of the sample:



## Photos of the Testing:

# TEST REPORT

NO.: ECT2019K040218-Y1

Date: Apr. 10, 2019

Page 4 of 4



\*\*\*End of Report\*\*\*