

Grafic de executie

a lucrarilor la obiectul: Reparatia capitala a imobilului cu nr. cad. 0100409.468.01 pe terenul cu nr. cad. 0100409.468, situat in mun. Chisinau sect. Riscani, str. Magda Isanos, 16.

		Month 1				Month 2				Month 3				Month 4				Month 5				Month 6				Month 7				Month 8			
		Week 1	Week 2	Week 3	Week 4	Week 5	Week 6	Week 7	Week 8	Week 9	Week 10	Week 11	Week 12	Week 13	Week 14	Week 15	Week 16	Week 17	Week 18	Week 19	Week 20	Week 21	Week 22	Week 23	Week 24	Week 25	Week 26	Week 27	Week 28	Week 29	Week 30	Week 31	Week 32
2-1-1 Demolare acoperis	Demolare acoperis	-----																															
	Demolari interioare	-----																															
	Demolari exterioare	-----																															
2-1-2 Consolidari interioare	Consolidari interioare													-----																			
	Structura de rezistenta la acoperis													-----																			
	Carcasa mono lit pentru lift													-----																			
2-1-3 Soluti arhitecturale	Specificatia elementelor lift L1													-----																			
	Timplarie													-----																			
7-1-1 Amenajari	Fatada													-----																			
	Lucrari de terasament													-----																			
	Fundatie													-----																			
	Gard de protectie													-----																			