

Act de primire-predare a lucrarilor efectuate nr. 1

MB SPRINTER

din 08.03.2025

Client cîd VIN: WDB907657KP068395
Adr juridica:
Recluzite bancare: Cîd la, BIC

Verificarea tehnica auto

Nr.	Denumirea m ² rilor (serviciilor)	Un. de masura.	Cantitate	Pret, MDL	Suma, MDL	Suma, TVA	Total
1	Scargire lichidul de racire						
2	Injectat N3 scapare ole						
3	Presiune						
4	Defectiune electrice la						
5	alternator						
6	Puncte excedentiale de rugina						
7	la caroserie						
8	Cauciucuri uzate 40%						
9	Nu corespund km parcursi						
10							
11	Verificat de mecanic auto						
12	Tornea H-						
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							

Total (incl. TVA):
Fara TVA.

Total acordate servicii in suma

Serviciile sus-mentionate au fost acordate in termenii stabiliti. Clientul nu are pretentii pentru calitatea serviciilor acordate.

Client/Reprezentant Client:
semnatura

L.S. dupa caz

