

TEST REPORT

Page 1/3

3F, Building Block 2, No. 3400 Gonghexin Road, Jing'an District - Shanghai 200436, P.R. CHINA 上海市静安区共和新路3400号2幢3层

Tél.: +86 21 68 55 50 32 Fax: +86 21 68 55 50 33 E-mail: ctcshanghai@ctcgroupe.com

naomizhou@lyncmed.com

Report No.: S200909071_2

For CE Marking: Yes

28 October 2020

APPLICANT: LYNCMED MEDICAL TECHNOLOGY (BEIJING)

CO., LTD (C41517)

ROOM1601, BUILDING NO. 2, ZHUBANG 2000 BUSINESS BUILDING, BALIZHUANG XIL199

CHAOYANG DISTRICT 100022 BEIJING

CHINA

Date of receipt :07 Sept. 2020 Testing period :10 Sept. 2020

:11 Sept. 2020

Sample description: Disposable nitrile gloves

Test(s) requested :-

Service :REGULAR Previous report :=

Brand / Section :-- Product category :=

Season --- Product type :=

End use :— Test stage :FIRST TEST

Factory name :-- Supplier name :-- Exported to :--

1. Conclusion:

Buyer: -

	Tests description	Conformity
	EN ISO 374-1	
1	Air Leak Test	Pass
2	Water Leak Test	Pass

Pass: requirements met Fail: requirements not met None: no requirement for this test N/A: not applicable

Approved by

Henry YAN Laboratory Manager



TEST REPORT

Page 2/3

28 October 2020 Report No.: S200909071_2

APPLICANT: LYNCMED MEDICAL TECHNOLOGY (BEIJING)

CO., LTD (C41517)

2. Sample(s) description assigned by laboratory:

Size	Analyzed product	<u>Description</u>	Sample information
	GLOVE		
		Whole glove	



200909071



TEST REPORT

Page 3/3

Report No.: S200909071_2

28 October 2020

APPLICANT: LYNCMED MEDICAL TECHNOLOGY (BEIJING)

CO., LTD (C41517)

3. GLOVE/

Whole glove

	Method	Client Requirement	Unit	Result	Conformity
• 5.2. Air Leak Test	EN 374-2:2019				Pass
Glove thickness			mm	0.10	
Air pressure used to test			kPa	3.5	
Result		No air bubbles		No air bubbles	
• 5.2. Water Leak Test	EN 374-2:2019				Pass
Result		No water leak		No water leak	

END OF TEST REPORT

•: The test was carried out by external accredited laboratory, not within their accreditation scope.