











实验室名称: 国家电器产品质量监督检验中心

Lab Name: China National Center for Quality Supervision and Test of Electrical Apparatus Products

№ 19XJ0631-S

检验(试验)报告 Test Report

委托单位: ZHEJIANG HAIVO ELECTRICAL CO.,LTD. Client:

产品名称: POLYMERIC STRAIN TYPE INSULATOR Name of Product:

产品型号: FXB-24kV/70kN

Product Type:

检验类别: Type test

Test Category:

检验检测专用章

本实验室对出具的检验(试验)结果负责,未经实验室书面同意, 不得部分地复制本报告。

The laboratory is responsible for the inspection (Test) results. The report shall not be reproduced except in full, written approval of the laboratory.



Total 48 Page 1

Keport II a.		Total 10 1 ago .
China National Center for Ouality Supervision and Test of	Test Rep	FXB-24kV/70kN POLYMERIC STRAIN TYPE
Electrical Apparatus Products		INSULATOR
The state of the s		

Contents

Number	Contents	Page
1	Cover	
2	Contents	1
3	General	2
4	Photos of the specimens	3
5	Test conclusion	4
6	Visual inspection	5
7	Mechanical routine test	6
8	Tests on interfaces and connections of end fittings	7~14
9	Hardness test	15
10	Accelerated weathering test	16
11	Tracking and erosion test	17
12	Flammability test	18
13	Tests on the core material	19~20
14	Assembled core load-time test	21
15	Dry lightning impulse withstand voltage test	22
16	Wet power-frequency test	23
17	Damage limit proof test and test of the tightness of the interface between end fittings and insulator housing	24
18	Verification of dimensions	25
19	Galvanizing test	26
20	Verification of the tightness of the interface between end fittings and insulator housing and verification of the specified mechanical load	27
21	Annex	28
22	Assembly	29
23	Oscillogram	30~48
	Blank below	
	•	

Report No.: 19XJ0631-S Total 48 Page 2 China National Center for FXB-24kV/70kN Quality Supervision and Test of Test Report POLYMERIC STRAIN TYPE **Electrical Apparatus Products INSULATOR** General Test category Type test Type and name of FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR specimens ZHEJIANG HAIVO ELECTRICAL CO.,LTD. Client CHONGSHI INDUSTRIAL ZONE, PANSHI, YUEQING, ZHEJIANG, CHINA Address Manufacturer ZHEJIANG HAIVO ELECTRICAL CO.,LTD. Address CHONGSHI INDUSTRIAL ZONE, PANSHI, YUEQING, ZHEJIANG, CHINA Manufacturing date and serial number lightning-impulse withstand voltage kV peak 190 Wet Power-frequency withstand voltage kV 100 Specified mechanical load (SML) kN 70 Creepage distance ≥645 mm parameters of specimens Main technical FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR Test commission form **Technical** data from FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR client Description Representative of client: Gu Guangwei Date of specimens receiving: Aug. 8th, 2019 Test period: From Aug. 12th, 2019 to Sep. 24th, 2019

Total 48 Page 4

China National Center for Quality Supervision and Test of		Test	Report	FXB-24kV/70kN POLYMERIC STRAIN			
Electrical Apparatus Products				INSULATOR			
Test conclusion							
Client ZHEJIANG HAIVO ELECTRICAL CO.,LTD.							
Type of specimens	FXB-24kV/70kN						
Name of specimens		IC STRAIN TYPE IN	SULATOR				
Manufacturer		HAIVO ELECTRICA					
TVIGITATION	Visual exam				PASS		
	A Residence of the second	routine test[SML: 70	0kN1		PASS		
			ns of end fittings (precond	dition test)			
	Tests on interfaces and connections of end fittings						
S 198 I		ry power frequency te	9				
			VALUE OF THE PARTY	load release pre-stressing)			
	Tests on inte	erfaces and connection	ns of end fittings (therma	l-mechanical pre-stressing)	PASS		
		ACCOUNT TO A CONTROL OF THE PARTY OF THE PAR	ns of end fittings (water i				
	Tests on inte	erfaces and connection	ns of end fittings (visual	examination)			
	455			ront impulse voltage test)			
				wer-frequency voltage test)			
	Hardness tes				PASS		
T 13	Accelerated weathering test						
Test items and results		d erosion test[1000h]		11 (12 (12 (12 (12 (12 (12 (12 (12 (12 (PASS		
Todato	ASSESSMENT TO SERVICE THE PROPERTY OF THE PROP	ty test [class V-0]	THE STATE OF THE S		PASS		
		core material (dye pe	netration test)		PASS		
	CHARLES OF SECURITION SECURITION	core material (water o			PASS		
		core load-time test[SN		100	PASS		
				per and lower end surfaces:			
	190kV peak	2000 C (20) C (2			PASS		
	Wet power-frequency test [between upper and lower end surfaces: 100kV/1min]						
		nit proof test and test		terface between end fittings	PASS		
	Verification	of dimensions[Accord	ding to technical deta]		PASS		
	Galvanizing	test[Ontology:single	average value≥70µm and	d total average value≥85μm]	PASS		
			e interface between end f nechanical load[SML: 7	ittings and insulator housing 0kN]	PASS		
	IEC61109:	2008 Insulators for ov	verhead lines - Composit	e suspension and tension insul	lators for		
Test standard	a.c. systems	with a nominal voltage	ge greater than 1 000 V -	Definitions, test methods and	ĺ		
	acceptance of	criteria		后量此会			
	The	tests are carried	out on FXB-24kV/70	kNPOLYMERIC STRAIN	TYPE		
1/4	INSULATOR by ZHEJIANG HAIVO ELECTRICAL CO., LTD., and the test items in						
Conclusion	relevant cla	auses of above test st	andards and technical sp	pecification, and the specimen	s have		
	passed the	tests.		specimens 检验检测专用章			
Note: the conclusion is valid only for the inspected and tested specimens.							
Compiled by:	A Pro	ofread by:	そ Checked by:) とり	Approved by: \	包		
Date:)0/9-11	Compiled by: Approved by: Party Checked by: Frank Approved by: Approved by: Date: 2019-11-18 Date: 2019-11-18						

Total 48 Page 5

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Visual examination

Test date: 2019-08-12

Test		4
PCT	Testi	и.

No. of the specimens	Appearance inspection standard of test specimen	Test result			
	Each insulator shall be examined. The mounting of	9			
	metallic parts on the insulator assembly shall be in				
	accordance with the drawings. The colour of the				
	insulator shall approximately be as specified in the				
	drawing.				
	The following defects are not permitted:				
	Superficial defects of an area greater than 25 mm ² (the	P. C.			
	total defective area not to exceed 0,2 % of the total	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
19XJ0631-S-#01~#22	insulator surface) or depth or height greater than 1 mm;	Meet the requirements			
	Crack at the root of the shed notably next to the metal				
	fittings;				
	Separation or lack of bonding at the housing to metal	16 Page 10 Pag			
	fitting joint (if applicable);	10/11/200			
	Separation or bonding defects at the shed to sheath	1868			
	interface(if applicable);				
	Moulding flashes protruding more than 1 mm above	2.944900 948			
	the housing surface.	12000			

Report No.: 19XJ0631-S China National Center for Quality Supervision and Test of Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE **INSULATOR**

Total 48 Page 6

Mechanical routine test

Test date: 2019-08-12

1. Test result				
No. of the specimens	Applied mechanical loads(kN)	Duration (min)	Whether damaged	
19XJ0631-S-#01	36.12			
19XJ0631-S-#02	35.55			
19XJ0631-S-#03	35.56			
19XJ0631-S-#04	35.60		,	
19XJ0631-S-#05	35.37			
19XJ0631-S-#06	35.31			
19XJ0631-S-#07	35.46			
19XJ0631-S-#08	35.39			
19XJ0631-S-#09	35.28			
19XJ0631-S-#10	35.29			
19XJ0631-S-#11	35.27	10	No	
19XJ0631-S-#12	35.76	10	140	
19XJ0631-S-#13	35.78			
19XJ0631-S-#14	35.80			
19XJ0631-S-#15	35.36	Salar Salar		
19XJ0631-S-#16	35.40	23.00		
19XJ0631-S-#17	35.39			
19XJ0631-S-#18	35.18			
19XJ0631-S-#19	35.16			
19XJ0631-S-#20	35.27			
19XJ0631-S-#21	35.28			
19XJ0631-S-#22	35.34			

Total 48 Page 7

China National Center for Quality Supervision and Test of Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Tests on interfaces and connections of end fittings (precondition test)

Test date: 2019-08-12

1 Test resu	lt
-------------	----

I LOSC YOU		
No. of the specimens	Appearance inspection standard of test specimen	Test result
19XJ0631-S-#01~#03	Three insulators assembled on the production line shall be used for tests on interfaces and connections of end fittings. Both end fittings shall be the same as on standard production insulators. The end fittings shall be assembled so that the insulating part from the fitting to the closest shed shall be identical to that of the production line insulator.	Meet the requirements



Total 48 Page 8

China National Center for Quality Supervision and Test of Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Tests on interfaces and connections of end fittings (reference dry power frequency test)

Test date: 2019-08-19

1. Test results:

No. of the Status of the		Dry power-frequency flashover withstand voltage (kV)				Average	Corrected	Duration	Puncture	
specimens	specimen or test part	1	2	3	4	5	value	value	(min)	Times
19XJ0631 -S-#01	Between	140.6	142.7	139.6	139.9	140.4	140.6	132.5	1	0
19XJ0631 -S-#02	upper and lower end surfaces of	143.1	140.4	138.7	141.5	140.9	140.9	132.8	1	0
19XJ0631 -S-#03	the insulators	138.3	140.1	140.5	140.7	141.3	140.2	132.2	1	0

Note: the data in the table has been corrected in the standard atmosphere condition.

Atmosphere condition of test zone

P=100.5kPa;

Environmental temperature t=28.5°C;

Relative humidity:72%

Atmosphere correction factor Kt=1.0609/1.0612/1.0605

Height correction factor Ka=/

Total 48 Page 9

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Tests on interfaces and connections of end fittings (Sudden load release pre-stressing)

Test date: 2019-08-12

1. Test requirement:

With the insulator at -20 °C to -25 °C, every test specimen is subjected to five sudden load releases from a tensile load amounting to 30 % of the SML.

Specified mechanical load SML: 70kN

2. Test results

Test temperature (°C)	Applied tensile load (kN)	Broken or not	
-21.3	21.01	Not	
-22.0	21.01	Not	
-21.5	21.00	Not	
-22.5	21.05	Not	
-21.5	21.03	Not	
	-21.3 -22.0 -21.5 -22.5	-21.3 21.01 -22.0 21.01 -21.5 21.00 -22.5 21.05	

Total 48 Page 10

China National Center for Quality Supervision and Test of Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Tests on interfaces and connections of end fittings (Thermal-mechanical pre-stressing)

Test date: 2019-08-12~2019-08-16

1. Test requirement:

Before commencing the test, the specimens shall be loaded at the ambient temperature by at least 5 % of the SML for 1 min, during which the length of the specimens shall be measured to an accuracy of 0.5 mm. This length shall be considered to be the reference length.

The specimens are then submitted to temperature cycles under a continuous mechanical load, the 24h temperature cycle being performed four times. Each 24h cycle has two temperature levels with a duration of at least 8 h, one at $(+50 \pm 5)$ °C, the other at (-35 ± 5) °C. The cold period shall be at a temperature at least 85 K below the value actually applied in the hot period. The pre-stressing can be conducted in air or any other suitable medium.

The applied mechanical load shall be equal to the RTL (at least 50 % of the SML) of the specimen. The specimen shall be loaded at ambient temperature before beginning the first thermal cycle.

After the test, the length shall again be measured in a similar manner at the same load and at the original specimen temperature.

Specified mechanical load SML: 70kN

2. Test results

No. of the specimens	Length of specimens (mm)	Applied tensile load (kN)	Cooling temperature	Heating temperature	Duration in cold or hot water (h)	Reversed times in 24h (times)	Length of specimens after test (mm)
19XJ0631-S -#01	485	35.04	-35.1	50.1	8	4	485
19XJ0631-S -#02	486	35.04	-35.1	50.1	8	4	486
19XJ0631-S -#03	485	35.04	-35.1	50.1	8	4	486

Total 48 Page 11

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Tests on interfaces and connections of end fittings (Water immersion pre-stressing)

Test date: 2019-08-16~2019-08-18

1. Test results:

No. of the specimens	Test liquor	Boiling time (h)	Whether cracks occur
19XJ0631-S-#01	Boiling deionized water with 0.1 % by weight of NaCl	42	No
19XJ0631-S-#02	Boiling deionized water with 0.1 % by weight of NaCl	42	No
19XJ0631-S-#03	Boiling deionized water with 0.1 % by weight of NaCl	42	No



Total 48 Page 12

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report


FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Tests on interfaces and connections of end fittings (Visual examination)

Test date: 2019-08-18

1. Test result

No. of the specimens	Appearance inspection standard of test specimen	Test result
19XJ0631-S-#01~#03	After water immersion pre-stressing the housing of each specimen is inspected visually. No cracks are permissible.	Meet the requirements



Total 48 Page 13

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE **INSULATOR**

Tests on interfaces and connections of end fittings (Steep-front impulse voltage test)

Test date: 2019-08-19

1. Test results:

No. of the	Specimen	Status of the	Positive	e polarity	Negative polarity		
specimens section		specimen or test part	Impulses in each section	Flashover or puncture	Impulses in each section	Flashover or puncture	
19XJ0631-S-#01	1	Between upper and lower of the shed	25	Flashover	Flashover 25		
19XJ0631-S-#02	1	Between upper and lower of the shed	25	Flashover	25	Flashover	
19XJ0631-S-#03	Between upper and lower of the shed		25	Flashover	Flashover 25		
Steepness Sp		pecified value		1000	~1500		
kV/μs	M	easured value	1004.7~1	329.3	1159.6~1300.8		
Conclusion	1000	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Pas	SS	0.000		

Atmosphere condition of test zone

P=101.1kPa;

Environmental temperature t=30.4°C; Relative humidity:63%

Atmosphere correction factor Kt=/

Height correction factor Ka=/

Total 48 Page 14

China National Center for		FXB-24kV/70kN
Quality Supervision and Test of	Test Report	POLYMERIC STRAIN TYPE
Electrical Apparatus Products		INSULATOR

Tests on interfaces and connections of end fittings (Dry power-frequency voltage test)

Test date: 2019-08-19

1. Test results:

No. of the	. specimen or				cy flashov ge (kV)	er	Average	Corrected	Duration	Times of
specimens			2	3	4	5	value	value	(min)	puncture
19XJ0631 -S-#01	Between	135.8	133.6	134.5	135.0	132.3	134.2	130.2	1	0
19XJ0631 -S-#02	lower end surfaces of	134.5	135.8	133.9	134.6	134.0	134.6	130.5	1	0
19XJ0631 -S-#03	the insulator	132.5	135.9	133.4	134.0	135.0	134.1	130.1	1	0

2. Conclusion: The values of flashover voltage of Specimens No.19XJ0631-S-#01~#03 exceed 90% of based flashover voltage and the test is passed.

	80% based		Measured points								
No. of the specimens	flashover voltage (kV)		Applied points	1	2	3	Average value	Temperature rise(<10K)	Results		
103/10/21			Refer to bar temperature (°C)	30.2	30.1	30.2	30.2				
-S-#01	19XJ0631 -S-#01 107.4	30	Temperature after raising voltage (°C)	30.4	30.2	30.3	30.3	0.1	Pass		
107/10/21	10	107.6	Refer to bar temperature ($^{\circ}$ C)	30.2	30.3	30.2	30.2		Pass		
19XJ0631 -S-#02	107.6		Temperature after raising voltage (°C)	30.4	30.5	30.3	30.4	0.2			
107/10/21			Refer to bar temperature ($^{\circ}$ C)	30.0	30.1	30.0	30.0				
19XJ0631 -S-#03	107.2	107.2	Temperature after raising voltage (°C)	30.3	30.2	30.4	30.3	0.3	Pass		

Note: based flashover voltage refers to dry power-frequency flashover withstand voltage of specimen 19XJ0631-S-#01~#03. See page 8

Note: the data in the table has been corrected in the standard atmosphere condition.

Atmosphere condition of test zone

P=103.2kPa;

Environmental temperature t=25.0°C;

Relative humidity:61%

Atmosphere correction factor Kt= 1.0309/1.0311/1.0308

Height correction factor Ka=/

Total 48 Page 15

China National Center for Quality Supervision and Test of Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Hardness test

Test date: 2019-08-15~2019-08-17

1. Test results:

N Cd	Ambient		Hardness Bo				Temperature	Ha	rdnes	Changement from the		
No. of the specimens	temperature (°C)	1	2	3	The mid- value	time (h)	after boiling (℃)	1	2	3	The mid- value	pre-boiled value < 20%
19XJ0631- S-C01	27.8	54.6	55.2	55.0	55.0	42	29.3	52.4	51.8	54.6	52.4	4.73
19XJ0631- S-C02	27.8	55.6	56.0	57.2	56.0	42	29.3	53.0	54.2	55.2	54.2	3.21

2. Conclusion: Pass

Total 48 Page 16

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Accelerated weathering test

Test date: 2019-08-12~2019-09-23

1. Test results:

No. of the	The temperature of blackboard		Radiancy	Duration (h)	Test results	
specimens	Required value	Set value	W/m ²	Duration (ii)	rest results	
17XJ0574-S-C03				1000	Markings on shed or housing material shall be legible; there are no surface degradations such as cracks and raised areas	
17XJ0574-S-C04	65°C±3K	65.3℃	550	1000	Markings on shed or housing material shall be legible; there are no surface degradations such as cracks and raised areas	
17XJ0574-S-C05				1000	Markings on shed or housing material shall be legible; there are no surface degradations such as cracks and raised areas	

2. Conclusion: Pass

Note: test method: UV light test

Total 48 Page 17

China National Center for Quality Supervision and Test of Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Tracking and erosion test

Test date: 2019-08-13~2019-09-24

1. Test result:

N <u>o</u> . of the	Applied	Creepage distance	Duration	Times of	Times of	-	f erosion m)
specimens	voltage (kV)	(mm)	(h)	flashover	interruption	Specified value	Measured value
19XJ0631-S- #04	19.95	690	1000	0	0	<3	<0.5
19XJ0631-S- #05	19.95	690	1000	0	0	<3	<0.5

After test the erosion depth does not reach the galvanized base. Corrosion resistance meets the requirement. The test is passed.

Note: Water velocity: $0.30L/(m^3 \cdot h)$; Fog house temperature: 20.0°C ; Concentration of NaCl in water: 8.0 kg/m^3 ; Settlement: $1.6mL/(80cm^2 \cdot h).19XJ0631\text{-S-}\#04$ is tested mounted horizontally and 19XJ0631-S-#05 is tested mounted vertically.

Total 48 Page 18

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Flammability test

Test date: 2019-08-14~2019-08-21

1. Test results:

N <u>o</u> . of the specimens	First ignition time (s)	t ₁ (s)	Second ignition time (s)	t ₂ (s)	t3 (s)	Individual test specimen afterflame time plus afterglow time after thesecond flame application (t2+t3) (s)	Total afterflame time tf (s)
19XJ0631-S-C06	10	0	10	0	0	0	
19XJ0631-S-C07	10	0	10	0	0	0	
19XJ0631-S-C08	10	0	10	0	0	0	0
19XJ0631-S-C09	10	0	10	0	0	0	
19XJ0631-S-C10	10	0	10	0	0	0	
19XJ0631-S-C16	10	0	10	0	0	0	
19XJ0631-S-C17	10	0	10	0	0	0	
19XJ0631-S-C18	10	0	10	0	0	0	0
19XJ0631-S-C19	10	0	10	0	0	0	
19XJ0631-S-C20	10	0	10	0	0	0	

Afterflame and/or afterglow of any specimen does not burned to the holding clamp and cotton indicator pad does not ignited by flaming particles or drops.

2. Conclusion: materials passing V-0

Note: specimens No. 19XJ0631-S-C06-C15 have preprocessed under temperature of $22.8\,^{\circ}\text{C} \sim 24.3\,^{\circ}\text{C}$ and humidity of 51%~54% for 48h; specimen No. 19XJ0631-S-C16-C25 have preprocessed under temperature of 70 $^{\circ}\text{C}$ for 168h.

China National Center for Quality Supervision and Test of Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Total 48 Page 19

Tests on the core material (Dye penetration test)

Test date: 2019-08-20

1. Test results:

No. of the specimens	Test liquor	Diameter of steel ball mm	The level which is higher than the level of the balls mm	Length of specimens mm	Time which dye rises through the specimens Specified value min	Time which dye rises through the specimens Measured value min
19XJ0631-S-B01		2.0	2.0	10.16	> 15	30
19XJ0631-S-B02	Allen	2.0	2.0	10.09	> 15	29
19XJ0631-S-B03		2.0	2.0	10.05	> 15	28
19XJ0631-S-B04	100 mg	2.0	2.0	10.11	>15	30
19XJ0631-S-B05	1% magenta alcohol	2.0	2.0	10.08	> 15	31
19XJ0631-S-B06	solution	2.0	2.0	10.07	> 15	30
19XJ0631-S-B07		2.0	2.0	10.12	> 15	29
19XJ0631-S-B08	Parador (Maria)	2.0	2.0	10.11	> 15	30
19XJ0631-S-B09		2.0	2.0	10.08	> 15	29
19XJ0631-S-B10		2.0	2.0	10.01	> 15	29

2. Conclusion: Pass

Total 48 Page 20

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Tests on the core material (Water diffusion test)

Test date: 2019-08-15~2019-08-20

1. Test requirements

Six specimens shall be cut from a production line insulator making the cut approximately 90° to the long axis of the insulator with a diamond-coated circular saw blade under running cold water. The length of the specimens h shall be 30 mm±0,5 mm. The cut surfaces shall be smoothed by means of fine abrasive cloth (grain size 180). The cut ends shall be clean and parallel.

The surfaces of the specimens shall be cleaned with isopropyl-alcohol and filter-paper immediately before boiling. The specimens shall be boiled in a glass container for 100 h±0,5 h in deionised water with 0,1 % by weight of NaCl.

Specimens of only one core material shall be boiled together in the same container. After boiling, the specimens shall be removed from the boiling container and placed in another glass container filled with tap water at ambient temperature for at least 15 min. The voltage test shall be carried out within the next 3 h after the removal of the specimens from the boiling container.

Immediately before the voltage test, the specimens shall be removed from the container and their surfaces dried with filter paper. Each specimen shall then be put between the electrodes. The test voltage shall be increased approximately 1 kV per second up to 12 kV. The voltage shall be kept constant at 12 kV for 1 min and then decreased to zero.

During the test no puncture or surface flashover shall occur. The current during the whole test shall not exceed $100\mu A$ (r.m.s.).

2. Test results:

No. of the specimens	The length of the specimens (mm)	Boiling time (h)	Whether damaged	Applied voltage (kV)	Duration (min)	Leakage current (mA)	Results
19XJ0631-S-B11	29.79	100	No	12.1	1	42	No puncture and surface flashover occurs
19XJ0631-S-B12	29.91	100	No	12.0	1	42	No puncture and surface flashover occurs
19XJ0631-S-B13	30.11	100	No	12.0	1	45	No puncture and surface flashover occurs
19XJ0631-S-B14	30.10	100	No	12.0	1	42	No puncture and surface flashover occurs
19XJ0631-S-B15	30.08	100	No	12.0	1	42	No puncture and surface flashover occurs
19XJ0631-S-B16	29.99	100	No	12.1	1	42	No puncture and surface flashover occurs

7	0		D
	Conc	lusion:	Pass
		COLUMN.	1 0000

Total 48 Page 21

China National Center for Quality Supervision and Test of Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Assembled core load-time test

Test date: 2019-08-14~2019-08-20

1. Test requirements

1. Determination of the average failing load of the core of the assembled insulator M_{AV}

Three of the specimens shall be subjected to a tensile load. The tensile load shall be increased rapidly but smoothly from zero to approximately 75 % of the expected mechanical failing load and shall then be gradually increased in a time between 30 s and 90 s until breakage of the core or complete pull-out occurs. The average of the three failing loads M_{AV} shall be calculated.

2. Verification of the 96 h withstand load

Three specimens shall be subjected to a tensile load. The tensile load shall be increased rapidly but smoothly from zero up to 60 % of M_{AV} , and then maintained at this value for 96 h without Failing (breakage or complete pull-out). If for any reason the load application is interrupted, then the test shall be restarted on a new specimen.

Specified mechanical load SML: 70kN

2. Test results of determination of the average failing load of the core of the assembled insulator MAV

No. of the specimens	75%SML (kN)	Time form 75% STL to failure (s)	Failing load (kN)	The average failing load M _{AV} (kN)
19XJ0631-S-#06	52.53	148	104.45	
19XJ0631-S-#07	52.51	169	111.59	108.16
19XJ0631-S-#08	52.53	160	108.44	

3. Verification of the 96 h withstand load

No. of the specimens	60%M _{AV} (kN)	Duration (h)	Whether damaged
19XJ0631-S-#09		96	No
19XJ0631-S-#10	64.90	96	No
19XJ0631-S-#11		96	No

4. Conclusion: Pass

Total 48 Page 22

China National Center for Quality Supervision and Test of Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Dry lightning impulse withstand voltage test

Test date: 2019-08-13

	Status of the	tus of the Positive polarity		Negative polarity			
No. of the specimen	specimen or test part	Voltage (kV)	Applied times	Puncture times	Voltage (kV)	Applied times	Puncture times
19XJ0631-S-#16	Between upper and lower end surfaces of the insulator	190.3	15	0	190.3	15	0

Note: the data in the table has been corrected in the standard atmosphere condition.



Atmosphere condition of test zone

P=103.2kPa;

Environmental temperature t=25°C;

Relative humidity:61%

Atmosphere correction factor Kt=1.0017

Height correction factor Ka=/

Total 48 Page 23

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Wet power-frequency test

Test date: 2019-08-13

	l component: 1.56mm/min omponent: 1.51mm/min	Conductance ratio: 98.6µS/cm Water temperature: 23.8			
No. of the section of	Status of the specimen	Power-frequence	cey withs	stand voltag	ge (Wet)
No. of the specimen	or test part	Voltage (kV)	Dura	ntion (s)	Puncture times
19XJ0631-S-#16	Between upper and lower end surfaces of the insulator	100.1		60	0

Note: the data in the table has been corrected in the standard atmosphere condition.



Atmosphere condition of test zone

P=103.2kPa;

Environmental temperature t=25°C;

Relative humidity:61%

Atmosphere correction factor Kt=1.0007

Height correction factor Ka=/

Total 48 Page 24

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Damage limit proof test and test of the tightness of the interface between end fittings and insulator housing

Test date: 2019-08-12~2019-08-16

1. Test results:

a. The four specimens are subjected to a tensile load applied between the couplings at ambient temperature. The tensile load shall be increased rapidly but smoothly from zero up to 70 % of the SML (49kN) and then maintained at this value for 96 h.

- 8				
	No. of the specimens	70%SML (kN)	Duration (h)	Whether damaged
	19XJ0631-S-#12	49.13	96	No
	19XJ0631-S-#13	49.13	96	No
	19XJ0631-S-#14	49.13	96	No
	19XJ0631-S-#15	49.13	96	No

b. At the end of the 96 h test 96h, both ends of specimen 19XJ0631-S-#12 shall be subjected to crack indication by dye penetration:

No. of the specimen		on of penetrant a cleaned surface (- 1000000000000000000000000000000000000	Whether there are cracks visible
19XJ0631-S-#12	14 A	20	建筑 建筑	No

c. The three remaining specimens are then again subjected to a tensile load applied between the couplings at ambient

temperature. The results as following:

No. of the specimens	75%SML (kN)	Time form 75% SML to SML (s)	SML (kN)	Duration (s)	Failing load (kN)	Fail Status
19XJ0631-S- #13	52.50	50	70.02	40	99.91	Separation
19XJ0631-S- #14	52.51	49	70.03	41	104.23	Separation
19XJ0631-S- #15	52.52	50	70.02	40	103.85	Separation

2. Conclusion: Pass

Total 48 Page 26

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Galvanizing test

Test date: 2019-08-12

1.	1. Test result Unit: μm												
No	Times/Thickness	1	2	3	4	5	6	7	8	9	10	Single average value	Required value
þ	19XJ0631-S-#20	127.1	108.2	100.5	96.0	95.5	93.4	102.0	95.3	104.5	86.1	100.9	≥70
Upper end	19XJ0631-S-#21	92.5	105.3	108.7	121.3	100.0	106.1	115.3	121.2	104.8	104.3	108.0	≥70
1	19XJ0631-S-#22	103.4	87.6	99.6	120.6	109.7	109.0	109.5	105.0	111.6	98.2	105.4	≥70
pı	19XJ0631-S-#20	109.8	108.7	115.4	111.8	118.3	104.0	112.6	106.3	107.9	105.8	110.1	≥70
Lower end	19XJ0631-S-#21	129.7	104.7	109.2	104.3	111.2	113.2	123.6	119.1	110.0	125.0	115.0	≥70
T	19XJ0631-S-#22	116.7	116.2	107.3	115.1	107.8	112.0	115.8	106.8	117.6	104.1	111.9	≥70
	Total average value Required total average value ≥85, Actual total average value: 108.5												

2. Conclusion: The coating is continuous, uniform and smooth. The coating is sufficiently adherent to withstand handing consistent with the normal use of the article, without peeling or flaking. It meets the requirements and the test is passed.

Total 48 Page 27

China National Center for
Quality Supervision and Test of
Electrical Apparatus Products

Test Report

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

Verification of the tightness of the interface between end fittings and insulator housing and verification of the specified mechanical load

Test date: 2019-08-12

1. Test result

a. One insulator, No.19XJ0631-S-#20 (selected randomly from the specimen E2), shall be subjected to crack indication by dye penetration, in accordance with ISO 3452, on the housing in the zone embracing the complete length of the interface between the housing and metal fitting and including an additional area, sufficiently extended, beyond the end of the metal part. After test no cracks are indicated. Within 5 min after the application of the penetrant, the insulator shall be subjected, at the ambient temperature, to a tensile load of 70 % of the SML, applied between the metal fittings; the tensile load shall be increased rapidly but smoothly from zero up to 70 % of the SML, and then maintained at this value for 1 min

No.of the specimen	Duration of penetrant applied on the cleaned surface (min)	Whether there are cracks visible	70%SML (kN)	Duration (s)	Whether damaged
19XJ0631-S -#20	20	No	49.81	60	No

b. The insulators of the specimen E1 shall be subjected at ambient temperature to a tensile load, applied between the couplings:

No.of the specimens	75% SML (kN)	Time form 75% STL to SML (s)	SML (kN)	Duration (s)	Whether damaged
19XJ0631-S -#16	52.57	50	70.31	40	No
19XJ0631-S -#17	52.56	50	70.26	40	No
19XJ0631-S -#18	52.53	50	70.28	40	No
19XJ0631-S -#19	52.56	50	70.31	40	No

2. Conclusion: Pass


Total 48 Page 28

Quality Supe	tional Center for ervision and Test of pparatus Products	Test Repo	ort	FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR
		Annex		
Serial number		Contents		N <u>o</u> .
1		Assembly		J
2	Oscillo	gram of mechanical routine t	est	/
3		ests on interfaces and connec Sudden load release pre-stress		1
4	Oscillogram of t	ests on interfaces and connec hermal-mechanical pre-stress	tions of end sing)	/
5		ests on interfaces and connect Steep-front impulse voltage to		1
6	Oscillogra	m of assembled core load-tin	ne test	
7	Oscillogram of da	y lightning impulse withstan	d voltage test	
8	Oscillogram o tightness of the in	f damage limit proof test and nterface between end fittings housing	test of the and insulator	/
9	between end fitting	erification of the tightness of gs and insulator housing and e specified mechanical load		/
ž.				
			23.473	
		ASHRELAND AND SERVE SA		
			A CONTRACTOR	
		The state of the s		
		1111		

Total 48 Page 30

Oscillogram of mechanical routine test


FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR




Total 48 Page 31

Oscillogram of mechanical routine test


FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR




FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR



FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR




FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR



FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR


N<u>o</u>.: /



Total 48 Page 36

Oscillogram of mechanical routine test

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR




Total 48 Page 37

Oscillogram of mechanical routine test


FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

N<u>o</u>.: /




Oscillogram of tests on interfaces and connections of end fittings (Sudden load release pre-stressing)

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR




Oscillogram of tests on interfaces and connections of end fittings (Sudden load release pre-stressing)

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR



Oscillogram of tests on interfaces and connections of end fittings
(Thermal-mechanical pre-stressing)

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR



Total 48 Page 41


Oscillogram of tests on interfaces and connections of end fittings (Steep-front impulse voltage test)

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR


No.: /

19XJ0631-S-#01

Positive polarity




Negative polarity




19XJ0631-S-#02

Positive polarity




Negative polarity




19XJ0631-S-#03

Positive polarity



Negative polarity




Report No.: 19XJ0631-S

Oscillogram of assembled core

load-time test


FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR



Total 48 Page 43

Oscillogram of assembled core load-time test

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR




Oscillogram of dry lightning impulse withstand voltage test

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR


No.: /

19XJ0631-S-#16


Positive polarity




Negative polarity




Positive polarity




Negative polarity



Positive polarity




Negative polarity



Total 48 Page 45


Oscillogram of damage limit proof test and test of the tightness of the interface between end fittings and insulator housing

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR




Oscillogram of damage limit proof test and test of the tightness of the interface between end fittings and insulator housing

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR



Oscillogram of verification of the tightness of the interface between end fittings and insulator housing and verification of the specified mechanical load


FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR



Oscillogram of verification of the tightness of the interface between end fittings and insulator housing and verification of the specified mechanical load

FXB-24kV/70kN POLYMERIC STRAIN TYPE INSULATOR

No.: /



No text below

DECLARATION

- 1. The report is invalid without special seal for testing and page combining seal on the report;
- 2. The report is invalid if altered;
- 3. The report is invalid without signatures of persons for drawing up, proof-reading, reviewing and approval;
- 4. The report is valid only for the inspected and tested samples.

NOTICE

- 1.In case there is any objection to this report, please raise it to the laboratory within fifteen days starting from the date of receiving the report. Thank you for your cooperation.
- 2.In case there is no objection, please take back the samples within one month starting from the date of receiving the report, when the manufacturer is going to take back the samples, certificate for sample taking and along with the written approval for the report should be brought in presence, only then the samples could be taken back. On time due, the samples will be in the laboratory's own disposal.

The Test Report is in total 48 pages including 20 figures and 1 photo

Proofreader

Chen jiwen

Binder Zhu Dengping

Address: No.5 Qianzhu Rd., Yuexi, Wuzhong District, Suzhou

Zhu Dengping

Tel: (0512) 66556600 68252753 68081201 Fax: (0512) 68081686

Post code: 215104 http://www.eeti.cn E-mail: eservice@eeti.cn



Typist