

FORMULARUL F3.3

GRAFIC DE EXECUTARE A LUCRĂRILOR

Lucrări de reparații interioare la grădinița nr. 223 din com.Tohatin-bucătăria, cabinetul metodic

N	Denumirea lucrarilor	ZILE																																															
		2	4	6	8	10	12	14	16	18	20	22	24	26	28	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45																		
	Lucrari de desfaceri si demontari																																																
	Bucatarie	+	+	+	+																																												
	Cabinet metodic	+	+																																														
	: Lucrari de reparatii generale																						+	+	+	+	+	+	+																				
	Bucatarie					+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+																										
	Cabinet metodic																		+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+				
	Lucrari instalatii sanitare si termice					+	+	+	+	+	+	+	+	+	+	+	+	+	+																														
	Bucatarie	+	+															+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+				
	Cabinet metodic	+	+															+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+			
	Lucrari de electromontaj																							+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+			
	Bucatarie	+	+																+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	
	Cabinet metodic	+	+																							+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	+	
	Lucrări la instalația de ventilație																																																
	Bucatarie	+	+	+												+	+	+	+	+	+	+	+	+	+																								
	Diverse								+																																						+		

Semnat: semnatura electronica

Nume/prenume: Buruiana D.

Funcția în cadrul firmei: Administrator

Denumirea firmei Euromontaj CTI SRL

