

SRL "Flerixon"

Graficul

Lucrari de reparatie a doua grupe la Gradinita de copii „Mugurel” din s. Casunca, rl. Floresti

Tipul lucrarilor	90 zile calendaristice			Total
11 Grupa Fluturasii				x
111 Demolari				x
112 Pardoseli				x
113 Pereti				x
114 Tavane				x
115 Timplarie				x
116 Incalzire				x
12 Grupa Buburuze				x
121 Demolari				x
122 Pardoseli				x
123 pereti				x
124 Tavane				x
125 Timplarie				x
126 Incalzire				x
2, Electricitate				x
2.2 Montare utilaj				x
2.3 Utilaj				x
TOTAL:				721605,78

Director SRL "Flerixon"