

TANK CONTAINER INITIAL INSPECTION REPORT

This certifies that the tank container has been re-inspected in accordance with ADR regulation current version

Scope: periodic inspection (2 ½ year inspection)

Place of inspection ADEN TRANSEXIM Chisinau Moldova

Operator/Lessor: ADEN TRANSEXIM Chisinau Moldova

Manufacture: VANHOOL

Manufacture serial nr.: 63773/TCIS20-21/I

BIC CODE ADTU 000005 - 8

Applicable regulation: ADR 2017

Tank information		Inspection Dates		
Tank code	P22D11	First Hydrotest Date	03/2000	
Serial no	63773/TCIS20-21/I	First Inspection Date	03/2000	
Year of manufacture	1995	Current Hydrotest Date	-	
Tara Weight	5040 kg	Current Inspection Date	09.12.2022	
Max Gross Weight	32000 kg	Next Inspection Date	08.06.2025	
Capacity	21000 liters	Next Hydrotest Date	08.16.2025	
Design t°	130°C			
Min. working t°	-40°C			
		Inspection	Satisfactory	Comments
Test pressure	6 bar	Internal	OK	-
MAWP	4 bar	External	OK	-
Top Outlet	Yes	Hydro/ Leak Tests		
Bottom Discharge	No	Test date Test	09.12.2022	
No of Closure in Series	3	pressure	6 bar	
Shell Material	D1N1.4404AIST316L	Valves	OK	-
Shell Thickness	4.4 mm	Fittings	OK	-
Head Material	D1N1.4404AIST316L	Frame	OK	-
Head Thickness	4.4 mm	Shell/Heads	OK	
Frame Dimns	30'x8'x8.6'			
Pressure Relieve Valves		Comments:		
	1 st	2 nd		
Manufacturer	Phoenix	Phoenix		
Serial No	129507/1/1	129507/1/2		
Full flow rate	21126SCFM	21126SCFM		
Operating pressure	124 psig	124 psig		
Vacuum setting	-	-		
Burst disk	No	No		

Issued at Chisinau

09.12.2022

Alexei Tkacenko

ADEN - TRANSEXIM

