

Report for the period from 05.08.2022 00:00 to 05.08.2022 23:59

Vehicle ODH_EURO_01_0019

Total route time, hours 00:13:34
Total distance, km 3.431741081111112
Average speed, km/h 15.07445563414634

Category	Total number of issues
Tank full	0
Container full	0
Pile of rubbish on asphalt paven	0
The presence of rubbish on asph	0
Asphalt pavement contaminatio	0
Unreadable road sign, signpost	41
Graffiti	249
Unreadable road markup	16
Road pavement damage	12
Unsatisfactory flower bed conte	0
Overflowing bin	1
Dirty light pole	7
Missing/damaged curb	0
Rail road crossing	0
Air conditioning	0
Satellite dish	0
Bilboard	0
Kiosk	0
Road works sign	0
Road sign	0
Inoperative street light	0
Traffic light	0
Registration number	0
Car	0
Face	0
Snow on the road	0
Dirty road	0
Slush road	0
Sand on the road	0
Snow on the road (BBOX)	0
Show piles on the road	0
Snow on the pedestrian zone	0