



CERTIFICATE

Hereby we certify that we have inspected on June 12, 2023, at WEBER-HYDRAULIK GMBH in Losenstein, Austria their BATTERY COMBI TOOL and supervised the tests conducted on the BATTERY COMBI TOOL.

SCOPE:**Rescue equipment****Brand name:** WEBER RESCUE SYSTEMS**Type:** SPS 370 MK2 S-FORCE**Article number:** 1101472**Nominal working pressure:** 70 MPa**CONCLUSION:**

The conclusions of our inspection are the following:

1. All tests complied with the standards EN 13204, 2016 edition and NFPA 1936, 2020 edition.
2. None of the tests caused malfunction to the equipment.
3. All the results from the tests were in compliance with the standards EN 13204, 2016 edition and NFPA 1936, 2020 edition.
4. All measurements were conducted correctly and the values were verified.

CLASSIFICATION:**ACCORDING TO EN 13204, 2016 edition**

Type	Classification	Cutting performance
SPS 370 MK2 S-FORCE	CK35/370H-19,7	1I-2J-3H-4J-5I

NFPA 1936, 2020 edition

Type	Classification	Cutting performance
SPS 370 MK2 S-FORCE	A7-B8-C7-D8-E8-F5	

THE COMPANY IS NEITHER AN INSURER NOR A GUARANTOR AND DISCLAIMS ALL LIABILITY IN SUCH CAPACITY. THE ABOVE REFLECTS OUR FINDINGS AT TIME AND PLACE OF INSPECTION. THIS CERTIFICATE DOES NOT RELIEVE SELLERS/SUPPLIERS FROM THEIR CONTRACTUAL RESPONSIBILITIES NOR DOES IT PREJUDICE BUYER'S RIGHT OF CLAIMS TOWARD SELLERS/SUPPLIERS FOR COMPENSATION FOR ANY APPARENT AND OR HIDDEN DEFECTS NOT DETECTED DURING OUR RANDOM INSPECTION OR OCCURRING THEREAFTER.

Place and date of issuance: Vienna, Austria, 20 June 2023

Inspector: Josef Resch

Teamleader: Bettina König

S.G.S. AUSTRIA
CONTROLL-CO. GES.M.B.H.
(AUTHORIZED AGENT OF
SOCIETE GENERALE DE SURVEILLANCE SA)

SGS Austria Controll-Co Ges.m.b.H
Grünbergstrasse 15
A-1120 Wien
t: +43 (1) 512 25 67-0
f: +43 (1) 512 25 67-9

Page 1 of 1

SGSPAPER
20539901



This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.

CERTIFICAT NR. 020101/61109



CERTIFICAT

Prin prezenta certificăm faptul că am inspectat la 12 iunie 2023, la WEBER-HYDRAULIK GMBH din Losenstein, Austria, SCULA COMBINATĂ CU ACUMULATOR și am supravegheat testele efectuate asupra SCULEI COMBinate CU ACUMULATOR.

DOMENIU DE APLICARE:**Echipament de salvare**

Numele mărcii:

WEBER RESCUE SYSTEMS

Tip:

SPS 370 MK2 S-FORCE

Număr articol:

1101472

Presiune nominală de lucru:

70 MPa

CONCLUZIE:

Concluziile inspecției noastre sunt următoarele:

1. Toate testele au fost în conformitate cu standardele EN 13204, ediția 2016, și NFPA 1936, ediția 2020.
2. Niciunul dintre teste nu a cauzat defecțiuni echipamentului.
3. Toate rezultatele testelor au fost în conformitate cu standardele EN 13204, ediția 2016, și NFPA 1936, ediția 2020.
4. Toate măsurătorile au fost efectuate corect, iar valorile au fost verificate.

CLASIFICARE:

ÎN CONFORMITATE CU EN 13204, ediția 2016

Tip	Clasificare	Performanță de tăiere
SPS 370 MK2 S-FORCE	CK35/370H-19,7	1I-2J-3H-4J-5I

NFPA 1936, ediția 2020

Tip	Clasificare	Performanță de tăiere
SPS 370 MK2 S-FORCE	A7-B8-C7-D8-E8-F5	

SOCIETATEA NU ESTE ASIGURĂTOR SAU GARANT ȘI ÎȘI DECLINĂ TOATĂ RĂSPUNDEREA ÎN ACEASTĂ CALITATE. CELE DE MAI SUS REFLECTĂ CONSTATĂRILE NOASTRE LA MOMENTUL ȘI LOCUL INSPECȚIEI. PREZENTUL CERTIFICAT NU EXONEREAZĂ VÂNZĂTORII / FURNIZORII DE RĂSPUNDEREA LOR CONTRACTUALĂ ȘI NU ADUCE ATINGERE DREPTULUI CUMPĂRĂTORULUI DE A SOLICITA DESPĂGUBIRI DE LA VÂNZĂTORI / FURNIZORI PENTRU ORICE DEFECTE APARENTE ȘI/SAU ASCUNSE NEDETECTATE ÎN TIMPUL INSPECȚIEI NOASTRE ALEATORII SAU CARE APAR ULTERIOR.

Locul și data emiterii: Viena, Austria, 20 iunie 2023

Inspector: Josef Resch

Șef de echipă: Bettina König

[Ștampilă S.G.S. AUSTRIA]

[Semnături indescifrabile]

S.G.S. AUSTRIA
CONTROLL-CO. GES.M.B.H.
(REPREZENTANT AUTORIZAT AL
SOCIETATE GENERALE DE SURVEILLANCE SA)

Prezentul document este emis, în numele Clientului, de către Societate în conformitate cu Condițiile Generale de Servicii tipărite pe verso. Se atrage atenția Clientului asupra problemelor de limitare a răspunderii, despăgubire și jurisdicție definite în acesta.

Orice alt deținător al acestui document este informat că informațiile conținute în acesta reflectă constatările Societății numai la momentul intervenției sale și în limitele instrucțiunilor Clientului, dacă există. Responsabilitatea exclusivă a Societății este față de Clientul său, iar prezentul document nu exonerează părțile implicate într-o tranzacție de exercitarea tuturor drepturilor și obligațiilor lor în temeiul documentelor tranzacției.

SGS Austria Controll-Co Ges.m.b.H
Grünbergstrasse 15
A-1120 Viena
t: +43 (1) 512 25 67-0
f: +43 (1) 512 25 67-9

Pagina 1 din 1

SGSPAPER 20539901 [Cod de bare]

[Sfârșitul traducerii]

Subsemnata Jebelean Andra-Ioana, traducător autorizat pentru limba ENGLEZĂ de Ministerul Justiției cu autorizația nr. 21178/2007, certific exactitatea traducerii din limba engleză în limba română a documentului supus traducerii.

Traducător,
JEBELEAN ANDRA-IOANA
Traducător și interpret
limba engleză
Aut. M.J.21178/2007